

CCD-Hobbs

Form 3160-5  
(August 1999)

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
Do not use this form for proposals to drill or to re-enter an  
abandoned well. Use Form 3160-3 (APD) for such proposals.

**FORM APPROVED  
OMB NO. 1004-0135**

Expires: November 30, 2000

5	Lease Serial No. NMLC069420
6	If Indian, Allottee or Tribe Name
7	If Unit or CA Agreement, Name and/or No.
8	Well Name and No. West Corbin No.8
9	API Well No. 300252978300
10	Field and Pool, or Exploratory Corbin South
11	County or Parish, State Lea County, New Mexico

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator EOG Resources, Inc.	
3a. Address P.O. Box 2267, Midland, TX 79702	3b. Phone No. (include area code) (915) 686-3608
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FNL & 1980' FWL Sec.17-T18S-R33E	

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>SI-Status</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

EOG Resources, Inc. respectfully requests a 6 month extension to evaluate the referenced well in order to determine whether to plug and abandon or to return to producing status.

**SI Approved For 3 Month Period  
Ending 3/1/2001**

**RECEIVED  
2000 SEP 25 A 11 40  
BUREAU OF LAND MGMT.  
DODGE, NEW MEX CO**

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

M. Lee Roark

Title Engineer Tech

Signature

*M. Lee Roark*

Date 09/19/2000

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

**(OMB. 200.) JOE G. LARA**

**Petroleum Engineer**

Date 12/1/2000

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct thereon.

Office **CFE**

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GWW