1370 1680

1880 2310

2000

1000

too

Form C-102

P. O. BOX 2088 ENERGY AND MINERALS DEFARTMENT SANTA FE. NEW MEXICO 875 All distances must be from the outer boundaries of the Section Operator Well No. Texaco Inc. New Mexico "Z" State NCT-5 Unit Letter Section Township Hance County 18-S Lea Actual Fastage Location of Well: 1850 2310 feet from the line and East feet from the Ground Level Elev. Producing Formation Dedicated Acreoge: 3997 Bone Springs North Airstrip Bone Springs 1. Outline the acrenge dedicated to the subject well by colored pencil or hachure marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc? If answer is "yes," type of consolidation Ycs If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.). No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, climinating such interests, has been approved by the Division. CERTIFICATION I hereby certify that the information comtoined herein is true and complete to the best of my knowledge and belief. Name B.L. Eiland Position Division Survevor Company Texaco Inc. (14)November 18, 1986 I hereby certify that the well location shown on this plat was platted from field 2310 notes of actual surveys made by me or under my supervision, and that the same true and correct to the best of my