New Mexico Cas Cossessiving and the second and the

1625 M. Zesser J. 1610 --Hobby N. 2010 1110 --

Form 3160-5 (August 1999) UNITED STATES
DEPARTMENT OF THE INTERIOR
BURFALLOF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

Expires November 30, 200

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side						7. If Unit or CA/Agreement, Name and/or No. NMNM84603X		
1. Type of Well ☐ Gas Well ☒ Other					8. Well Name and No.			
2. Name of Operator					Central Corbin Queen Ut #212 9. API Well No.			
Saga Petroleum LLC 3b. Phone No. (include of				code)	30-025-29798			
^{3a.} Address 415 W . Wall, Suite 1900, N	(915)684-4293			10. Field and Pool, or Exploratory Area Corbin Queen				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL & 560' FWL Sec. 3 (E), T18S, R3/E 33					11. County or Parish, State Lea NM			
12. CHECK AP	PROPRIATE BOX(ES)	O INDICATE 1	NATURE (OF NOTICE,	REPORT, C	OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
☐ Notice of Intent ☐ Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Fracture Trea ☐ New Constru		Production (Sta Reclamation Recomplete	rt/ Resume)	 □ Water Shut-Off □ Well Integrity □ Other Add perf 	fs	
Final Abandonment Notice	Change Plans Convert to Injection	☐ Plug and Aba	andon 🗌	Temporarily A Water Disposa				
9-25 RIH w/4-3/4" bit 4219'- 4220', 24 holes. RI 9-26 Set treating pkr & 60 ball sealers. Avg rat No Ball action. Flushed to 9-27 Injected 122 BW 9-28 Injected 200 BW pkr fluid, set pkr. Press to 2-3/8" lined tbg (4075') 2-	for final inspection.) /H, NU BOP, release p & tbg, cleaned out fror D Computalog. RIH w/N @ 4091', RU Cudd, Pr e 4 BPM, Avg press 28 b btm perf. RD Cudd, N @ 11120 psi in 22 hrs @ 1600 psi - Bled well b 580 psi - good test wit -3/8" x 5t-1/2" AD-1 pkr	kr, tag up 3' be m 4080'-4236' (VS & treating p ess up on csg t 85 psi, ISIP 22 IU well for inject dwn, release p	low pkr @ (PBTD) . F okr to 4100 to 350 psi, 275 psi, 5 r ction & retu kr & POO y Robinso	4080', POC POOH w/WS O'. Leave pkr Acidize per mins 2092 p urn well to in	oH w/tbg , RU Comp swinging fs 4190'-42 si, 10 mins j RIH w/AD Return well	putalog & perf'd 419 220' w/2500 gal 15% 1939 psi, 15 mins -1 pkr & inj tbg, ND to active injection	90'-99' & 6 Acidtrol 1833 psi. 9 BOP, circ - 134 jts	
10-2 Injected 173 BW @ 1800 psi Original chart to Hobbs OCD w/copy this form -						ACCEPTED FOR RECORD		
Copy chart on back of or	iginal form to Roswell E	3LM & copy for	m & chart	to BLM Car	lsbad (OCT - 9 2002		
14. I hereby certify that the foregoi Name (Printed/Typed)	ng is true and correct		Title			SARY GOURLEY		
Bonnie Husband			Production Analyst		PETROLEUM ENGINEER			
Signature Bonnie	Bustand		Date 10/03/20		ICE			
	THIS SPAC	E FOR FEDERA	Titl		7512	Date		
Conditions of approval, if any, are certify that the applicant holds legal which would entitle the applicant to	or equitable title to those rights conduct operations thereon.	in the subject lease	Offic	ce				
Title 18 U.S.C. Section 1001, mak fraudulent statements or representa	es it a crime for any person know tions as to any matter within its j	ringly and willfully to urisdiction.	make to any	department or age	ncy of the Unit	ed States any false, fictitiou	s or	

