STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

48. 87 COFIE SCLEIVED	
DISTRIBUTION	
SANTA FE	
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	 †

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 .

SANTA FE	SANTA FE,	NEW MEXICO 875	101		Revised 10-1-7
FILE			· · · · · · · · · · · · · · · · · · ·	5a. Indicate Ty	pe of Lease
U.S.G.S.				State 🔀	Fao 🗌
OPERATOR	•			5. State OII & C	Gas Lease No.
<u></u>				LG 5	682
SUNDRY [DO HOT USE THIS FORM FOR PROS USE "APPLICATE"	Y NOTICES AND REPORT	SON WELLS PLUG BACK TO A DIFFERENT FOR SUCH PROPOSALS.	RESERVOIR.		
1.				7. Unii Agreem	ent Name
MELL A MELL .	OTHER-				
2. Name of Operator		<u> </u>		8. Form or Lea	se Name
Yates Petroleum Corp	oration				Star AEA S
J. Address of Operator	,			9. Well No.	
105 South 4th St., A	rtesia, NM 88210) 		1	
4. Location of Well					Pool, or Wildcat
UNIT LETTER J . 165	O FEET FROM THE S	South LINE AND 23	10 PEET PROM	a. seveen	Sone Springs
Foot	7 7	100	0577		
THE BAST LINE, SECTION	N 11 TOWNSHIP	180 RANGE	35E NMPM.	الللللة	
	15. Elevation (Show u	hether DF. RT. GR. etc.)		12. County	744444
		891.1' GR		Lea	
16. Chark A	~~~~		. D Oak		
NOTICE OF IN	appropriate Box To Indic	ate Nature of Notic	e, Report of Uth SUBSEQUENT		- .
NOTICE OF IN	TENTION TO:		SOBSEQUENT	REPORT OF	•;
PERFORM REMEDIAL WORK	PLUG AND ABANDO	N REMEDIAL WORK		ALT	ERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLI	NG OPHS.		AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND	 		
		OTHER Int	ermediate Cas	sing	5
ОТНЕЯ		_ 🔲	•		_
17. Describe Proposed or Completed Ope	erations (Clearly state all pertin	ent details, and give nertic	ent dates including	estimated date c	Cetating any propose
work) SEE RULE 1 fos.	antions (dream) state and perior	ent details, and give perm	iem dates, metading	.stmateu unte o	y starting any proposes
Ran 92 joints 8-5/8" Float collar set 376 and 1/4# Celloseal. 14.8). PD 2:15 AM 1 float held okay. Ce 1-7-87. WOC 22 hour okay. Reduced hole	88'. Cemented w/Tailed in w/250 -6-87. Bumped pement circulated s and 15 minutes	1200 sacks Pa sacks Class lug to 1950 p 56 sacks to p . NU and tes	cesetter Li "C" Neat (y si, release it. WOC. ted to 1000	te with ield 1.3 d pressu Drilled psi for	5# salt 2; weight re and out 12:30 A
	•				•
i8. I hereby certify that the information a			1		
io. I negeby certify that the information a	nove is true and complete to the	e best of my knowledge and	Deliel.		
(· · · · · /).	2.	Production S	upervisor		1-8-87
icheo (anda /)	DULIN TITLE			DATE	
ORIGINAL SIGNED BY JE DISTRICT I SUPER	RRY SEXTON VISOR		·.	. 61	IN 1 4 1987
Millian					