				and the second secon
			203 CH. C. SALECCA	T RANGAS Marina La
Form 3160-5	UNITED STAT	•• — •	1625 N. Frenc 1625 N. Frenc	FORM APPROVED
(June 1990)	DEPARTMENT OF THE BUREAU OF LAND MA		1625 N. Frent Hobbs, NM	Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS			e	5. Lease Designation and Serial No. NM51846
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals				6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE				7. If Unit or CA, Agreement Designation
1. Type of Well				
Oil Gas Well □ Other				8. Well Name and No.
2. Name of Operator BTA OIL PRODUCERS				EK 'B', 8701 JV-P, #1
3. Address and Telephone No.				9. API Well No. 30-025-29874
104 South Pecos, Midland, TX 79701 915/682-3753				10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2130' FNL & 625' FWL				EK, Delaware
Sec. 30, T18S, R33E SW/NW				11. County or Parish, State
10 01/201/10/201				Lea
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION				
THE OF ACTION				
X Notice of Intent				Change of Plans
Subsequent Repo	ort	Recompletion		New Construction
· ·		Plugging Back		Non-Routine Fracturing
Final Abandonme	nt Notice	Altering Casing		Uter Shut-Off
		Other		Dispose Water
				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
 13. Describe Proposed or Completed Operations (Clearly state all pertinet details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markders and zones pertinent to this work.)* 1) MIRU - ND wellhead; NU BOP. POH w/ prod. equipment 2) PU CIBP for 5-1/2" 17# csg on tbg. RIH. Set CIBP @ +/-9420' 3) Load hole w/ 2% KCI wtr & circ. bottoms up. Raise tbg to 8927'. Spot 200 gals 10% acetic acid @ 8927' POH w/ tbg. 4) RU & perforate 8923' - 8927' w/ 2JSPF. Spot 40' cmt on top of CIBP w/ dump bailer. 3) RIH w/ tbg & pkr, pressure testing tbg to 8000 psi. Set pkr @ 8700' 6) Swab back load to evaluate 				
14. I hereby certify that the totegaring Signed Control of Federal or State offic Office. SGIV (Approved by Conditions of approval, if any:	is the sto correct	Regulatory Admin	istrator	Date 09/30/99 Date 01 1999
Title 18 U.S.C. Section 1001, makes i statements or representations as to a	it a crime for any person knowingly and ny matter within its jurisdiction.	I willfully to make to any d	epartment or agency of the United	J States any false, fictitious or fraudulent

GWW

s L