

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL **GAS WELL** **OTHER**

2. NAME OF OPERATOR
Mewbourne Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 7698, Tyler, Texas 75711

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL & 1650' FEL

14. PERMIT NO. 30-025-29954

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3782.7' GR

5. LEASE DESIGNATION AND SERIAL NO.
NM-0554244

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal "L"

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Querecho Plains - Upper
Bone Springs

11. SEC., T., R. M., OR BLK. AND SURVEY OR AREA
23-18S-32E

12. COUNTY OR PARISH Lea

13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	FULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Set production string</u>	<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/12/87 - Ran guide shoe, 42.71' shoe joint, float collar, 13 centralizers, 52 joints 5-1/2" 20# N-80 LT&C (2158.61'), 71 joints 5-1/2" 17# N-80 LT&C (2940.45'), 84 joints 5-1/2" 20# N-80 LT&C (3562.04'). Total 8706.23', set at 8698'. Western cemented with 1000 sxs of Pacesetter and 475 sxs of Class "H" lite with 6% gel + 5#/sx salt. PD to 8652' at 11:30 P.M. Did not circulate cement.

RECEIVED
JUL 24 11 11 AM '87
CARLSBAD RESOURCE
AREA HEADQUARTERS

ACCEPTED FOR RECORD
JUL 20 1987
SJS
CARLSBAD RESOURCE

18. I hereby certify that the foregoing is true and correct

SIGNED *Clyde Thompson* TITLE Engr. Oprns. Secretary DATE 7/20/87

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side