

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
LG 1543

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Cities Service Oil & Gas Corp.	8. Farm or Lease Name State DW
3. Address of Operator P. O. Box 1919, Midland, Texas 79702	9. Well No. 7
4. Location of Well UNIT LETTER E, 1930 FEET FROM THE North LINE AND 835 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 18S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Mescalero Escarpe (Bone Springs)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. @ 8950' Dolomite Lime & Shale. Plugged and Abandoned. Drilled a 7 7/8" hole from 3170' to a T.D. of 8950' in Dolomite Lime & Shale and after receiving verbal approval from Jerry Sexton w/NMCD in Hobbs, NM, this well was P & A'ed in the following manner:

1. Set 38 sx. CL. H cement plug @ 8700' - 8600' across top of Bone Springs Second Dolomite.
2. Set 38 sx. CL. H cement plug @ 8200' - 8100' across top of Bone Springs 1st Dolomite.
3. Set 34 sx. CL. H cement plug @ 6650' - 6550' across top of Dolomite.
4. Set 44 sx. CL. H cement plug @ 4450' - 4350'
5. Set 43 sx. CL. H cement plug @ 3220' - 3120' 1/2 in & 1/2 out of 8-5/8" csg. shoe @ 3170'.
6. Set 29 sx. CL. H cement plug @ 400' - 300' 1/2 in & 1/2 out of 13-3/8' csg. shoe @ 370'.
7. Set 10 sx. CL. H. cement plug @ 30' to surface.

Set A 4" Dry Hole Marker 4' above ground to designate a P & A Location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.A. Votran TITLE District Oper. Mgr. - Prod. DATE 8-19-87
APPROVED BY R. A. [Signature] TITLE OIL & GAS INSPECTOR DATE JAN - 4 1988
CONDITIONS OF APPROVAL, IF ANY: