

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other Instruction
(Reverse side)

DATE

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-067229-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

M. T. Keohane Federal

9. WELL NO.

3

10. FIELD AND POOL OR WILDCAT

Mescalero Escarpe

Bone Springs

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA

Sec. 14, T-18-S, R-33-E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Drilling Well

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

Unit Letter D, 330' FNL and 990' FWL

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3991 KB

16. Check appropriate box to indicate nature of notice, report, or other data

TEST WATER SHUT-OFF ☐ PUMP OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ DIST. & CHANGE PLUG ☐
(Other) ☐

SUBSEQUENT REPORT OF:
WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) Production Csg / Cement

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is being drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.

Drilled 7 7/8" hole to 9050' TD at 4 pm MST 9-5-87.
Ran Jts, 9037' 5 1/2" csg (2132' L-80 17" LT+C, 2015' J-55 17" LT+C, 4847' J-55 15.5" LT+C, and 43' L-80 17" on Top).
Set @ 9050', F.C. @ 8964', D.V. Tool @ 6990'. Cemented 1st stage w/300 sx 'H' Lite w/1/4" flocele and 250 sx 'H' w/.6% Halad-9 + 1/4" flocele. Plug down 11:15 AM, open D.V. tool circ. 100 sx to pit. 2nd stage 1000 sx 'H' lite w/1/4" flocele, Plug down 7:15 pm, Circ. 120 sx.

18. I hereby certify that the foregoing is true and correct

SIGNED A. Germandt

TITLE Area Superintendent
305-393-4031

DATE 9-18-87

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

SEP 23 1987

SJS

*See Instructions on Reverse Side

CARISBAD, NEW MEXICO

RECEIVED
SEP 24 1987
OCC
HOBBS OFFICE