

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-29988

5. Indicate Type of Lease

STATE ☒ FEE

6. State Oil / Gas Lease No.

B-3011

7. Lease Name or Unit Agreement Name

NEW MEXICO Z STATE NCT-1

8. Well No.

1

9. Pool Name or Wildcat

~~VACUUM GRAYBURG~~ SWD, 96121 SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL GAS WELL OTHER SWD WELL

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter 3/C 660 Feet From The NORTH Line and 2200 Feet From The WEST Line
Section 2 Township 18S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4017' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☒ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐
OTHER: ☐ OTHER: ☐ CONVERT TO DISPOSAL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-28-00: MIRU REV UNIT. MIRU PU.

7-05-00: NDWH. NUBOP. TIH W/BIT, CSG SCRAPER. TAG PBTD @ 5958'. PULL BIT TO 5114'. CIRC W/150 BBLS 2% KCL WTR. TEST CSG & PLUG & CHART TO 500# FOR 30 MINS.

7-06-00: TIH W/GR/CCL & LOG 5957-4500'. TIH W/PERF GUN & PERF 4894-5080'. TIH W/CIBP & SET @ 5505'. TIH W/PKR, SN, & TBG. STOP PKR @ 1600'.

7-07-00: TIH W/TBG TO 5076'. SPOT 4 BBLS 20% NEFE HCL ACR PERFS 5080-4894'. PULL UP & SET PKR @ 4790'. TEST BACKSIDE TO 500#-OK. ACIDIZE PERFS 4894-5080 W/10,000 GALS 20% NEFE HCL. FLSH W/35 BBLS FW. FLOWBACK.

7-10-00: OPEN BY-PASS ON PKR & CIRC HLE W/130 BBLS 10# BRINE. REL PKR & LOWER TO 5235'. NO SALT FILL. STOP PKR @ 1600'.

7-11-00: NDBOP. FLANGE UP TBG.

7-12-00: PUMP 120 BBLS 2% PKR FLUID. SET PKR @ 4852'. PRESS TEST CSG & PKR & CHART FOR NMOCD TO 530# FOR 30 MINS. PUMP 30 BBLS 10# BRINE DN TBG.

1-25-01: ON 24 HR OPT. CHANGE STATUS TO SHUT IN SWD WELL. FINAL REPORT

(CHARTS ATTACHED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant

DATE 1/24/01

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE

DATE

DeSoto/Nicols 12-93 ver 1.0

JCSN

8



