

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-30397
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2229
7. Lease Name or Unit Agreement Name: Philmax
8. Well No. 33
9. Pool name or Wildcat Malimar / Grayburg San Andres
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4178' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	4. Well Location Unit Letter B : 660 feet from the North line and 1980 feet from the East line Section 28 Township 17-S Range 33-E NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4178' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03/19/02 MIRU BASIC ENERGY SERVICES P & A PACKAGE #2282. OBJECTIVE: PLUG AND ABANDON "PHILMEX #33", LOCATED: 660' FNL & 1980' FEL, SEC 28, T-17-S, R-33-E, LEA COUNTY, NEW MEXICO. NOTIFIED NMOCD SYLVIA DICKEY W/ INTENT TO COMMENCE P & A OPERATIONS. DIG TESS #202101204. ND WH, NU CLASS 1 BOPE. RIG UP FLOOR, GIH W/ CIRC - 3940'. WAIT ON WATER AND PUMP. CIRC THROUGH AND ATTEMPT TO SET CIRC. WOULD NOT SET. POOH W/ CIRC. GIH W/ CIRC. SET CIRC @ 3940', ATTEMPT TO CIRC BELOW CIRC. NO CIRC RATE. 1500#, NO BLEED OFF. UNSTING FROM CIRC, MIX 20 SX SALT GEL, CIRC WELL. WAIT ON APPROVAL FROM NMOCD. * NOTE: ALL PLUGS = CLASS "C" CEMENT, 14.8#, 1.32 YD. PUMP PLUG #1 (35 SX, INTERVAL 3940'-3587', DISPLACE W/ 13 BEL MLF (MUD LADEN FLUID)). RECEIVED APPROVAL FROM NMOCD GARY WINK, TO SET PLUG ON TOP OF RETAINER AND NOT REQUIRED TO TAG. POOH - LD WS TO 2780'. PUMP PLUG #2 (25 SX, INTERVAL 2780'-2527', DISPLACE W/ 9 BEL MLF). POOH - LD WS TO 1630'. PUMP PLUG #3 (30 SX, INTERVAL 1630'-1327', DISPLACE W/ 4.5 BEL MLF. POOH. SECURE WELL. SDON.

** CONTINUED ON BACK **

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stacey M. Sanders TITLE Supervisor, Reg./Pro. DATE 04/01/02
Type or print name L. M. Sanders Telephone No. 915/368-1488

(This space for State use)
APPROVED BY Johnny Robinson TITLE COMPLIANCE OFFICER DATE NOV - 1 2002
Conditions of approval, if any: GWW

Continued:

PHILMEX #33

03/20/02 TRAVEL TO LOCATION. FINISH POOH, LAY DOWN CICR STINGER. GO IN HOLE. TAG PLUG #3 @ 1326'. POOH - LD WS TO 400'. PUMP PLUG 4 (40 SX, INTERVAL 400'-SURFACE). POOH, LD WS. CLEAN OUT AND ND BOPE. RDMO BASIC ENERGY SERVICES P & A PACKAGE # 2282. PERFORM RECLAMATION, CUT OFF WELLHEAD, CAP AND INSTALL DRY HOLE MARKER. P & A OPERATIONS COMPLETE. DROP FROM REPORT.

MATERIAL TRANSFER:

#799492 - WELLHEAD AND ACCESS.