

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

| |
|---|
| WELL API NO. 30-025-30595 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. K-3581-1 |
| 7. Lease Name or Unit Agreement Name Lea 946 State |
| 8. Well No. 4 |
| 9. Pool name or Wildcat Buckeye <i>also</i> |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3905' GR |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER | |
| 2. Name of Operator Hondo Oil & Gas Company | |
| 3. Address of Operator P. O. Box 2208, Roswell, NM 88202 | |
| 4. Well Location Unit Letter <u>G</u> : <u>2307</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>3</u> Township <u>18S</u> Range <u>35E</u> NMPM Lea County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3905' GR | |

| | |
|---|--|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged as follows:

- (1) CIBP was set @ 8054' with 35' of cement on top
- (2) jet cut 5 1/2" casing @ 7000' and pulled
- (3) spotted 40 sx. cement plug in and out of 5 1/2" casing stub from 7050-6771'
- (4) CIBP was set @ 4687'
- (5) set 40 sx. cement plug from 4430-4330'
- (6) set 50 sx. cement plug from 3663-3485'
- (7) set 35 sx. cement plug from 30' to surface
- (8) cut off wellhead and installed dry hole marker 5/11/90

Plugging procedure per Paul Kautz, NMOCD-Hobbs District Office.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lisa Bohannon TITLE Engineering Technician DATE 7/16/90
TYPE OR PRINT NAME Lisa Bohannon TELEPHONE NO. 505/625-6739

(This space for State Use)

APPROVED BY [Signature] TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: