

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

October 28, 1993

CERTIFIED RETURN RECEIPT

Woodbine Petroleum, Inc.
1445 Ross Ave.
LB 234 Suite 3660
Dallas, TX 75202

Gentlemen:

Enclosed please find a copy of form C-108 (Application for Authority to Inject) on Yates' Aqueduct SWD #1 located in Unit P of Section 17-T19S-R32E.

Should you have any questions, please feel free to contact me at (505) 748-1471.

Sincerely,

Jim Brown
Operations Engineering Supervisor

JB/sj

Enclosure