

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30608
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LG-6631
7. Lease Name or Unit Agreement Name Cal-Mon 15 State
8. Well No. 1
9. Pool name or Wildcat Mescalero Escarpe Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Harvey E. Yates Company	
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>15</u> Township <u>18S</u> Range <u>33E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3926.4 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-11-89 Perf 8717, 8714, 8710, 8704, 8325, 8321, 8316 and 8311 (2 JSPF 16 holes).
8-12-89 Acdz perfs 8704-17'w/4250 gals 20% SRA
8-15-89 Acdz perfs 8316-25'w/4250 gals 20% SRA
8-16-89 Perf 8785-93 (1 JSPF 9 holes).
8-17-89 Acdz 8785-93 w/2000 gals 20% SRA. Communicated w/perf @ 8704-17'
8-19-89 Acdz perfs 8704-17' & 8795-93' w/1000 FW, 7500 gals 15% SRA-100 and 7500 gals
over flush
8-23-89 Set CIBP @ 8425
8-24-89 Set 5 1/2" cmt retainer @ 8225', Squeeze perfs 8311-25 w/221 SX Class "H" cmt.
8-25-89 Drill out ret., cmt & test to 1500#, held ok, drill out CIBP @ 8425'
8-27-89 Run SN to 9500' and anchor to 8214', run pump & rods. Hang on production
to pump perfs 8704-9431

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray T. C. [Signature] TITLE Production Manager/Engineer DATE 8-31-89
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

SEP 5 1989

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: