



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
HOBBS DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

October 2, 1989

POST OFFICE BOX 11880
HOBBS, NEW MEXICO 88241-1880
(505) 393-6161

Southland Royalty Company
21 Desta Drive
Midland, TX 79705

Attn: Robert L. Bradshaw

Re: West Corbin Federal #16-0
Section 7, T18S, R33E

Gentlemen:

We received a copy of your application to drill the above-referenced well from the BLM and it is noted your location, 990/S and 1980/E of Section 7, is unorthodox for the South Corbin Wolfcamp Pool. The special pool rules require the well to be located within 150 feet of the center of any quarter/quarter section. It will be necessary for you to obtain approval of this unorthodox location prior to producing the well.

If you have questions concerning this, please contact Evelyn Downs at (505) 393-6161.

Very truly yours,

OIL CONSERVATION DIVISION

Jerry Sexton
Supervisor, District I

ed

Handwritten note:
Location
990/S + 1980/E
South Corbin Wolfcamp Pool