State of New Mexico Submit 3 Copies Form C-103 to Appropriate District Office Energy, Minerals and Natural Resources Department Revised 1-1-89 DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 30-025-30717 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATE FEE L DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. 857948 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) VACUUM GRAYBURG SAN ANDRES UNIT Type of Well: OAS WELL WELL X OTHER 2. Name of Operator 8. Well No. TEXACO PRODUCING INC. 157 3. Address of Operator 9. Pool name or Wildcat P. O. Box 3109 Midland, Texas 79702 VACUUM GRAYBURG SAN ANDRES 4. Well Location 710 Feet From The NORTH 2530 Feet From The WEST Line and _ Line Section . Township 18-SOUTH Range 34-EAST **NMPM** LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3993', KB-4006' Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: COMPLETION X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1. MIRU DA&S. CLEAN OUT TO PBTD OF 4990'.
- 2. PENWOOD RAN GR-CNL-CCL FROM 4990' TO 3990'. PERF w/ 2 JSPF: 4436-42, 4446-50, 4455-60, 4464-74. 4496-4509, 4525-39, 4547-55, 4562-68, 4664-70, 4676-80. 152 HOLES. WESTERN ACIDIZED w/ 7500 GAL 15% NEFE. TIH w/ RBP. SET @ 4390' & TEST TO 3000#.
- 2. PENWOOD PERF w/ 2 JSPF: 4282-84, 4291-93, 4300-08, 4313-16, 4320-31, 4344-48. 60 HOLES. WESTERN ACIDIZED w/ 4000 GAL 15% NEFE. SWAB 7 HRS. REC 7 BNO, 6 BW & 178 BLW. MOVE RBP TO 4268'. TEST TO 3000#. 3. PERF w/2 JSPF: 4178-82, 4194-98, 4204-12, 4230-41, 4254-58. 62 HOLES. WESTERN ACIDIZED w/ 4100 GAL

		. SEATING NIPPLE @ 4880'. 34 BNO & 797 BW.	
•	s is true and complete to the best of my kno	wiedge and belief.	***************************************
SIGNATURE C.P. Busham/CWH		TITLE DRILLING SUPERINTENDENT	DATE 08-21-90
TYPEORPRINTNAME C. P. BASHAM			TELEPHONE NO. 915-6884620
(This space for State Use)	Paul Linus z g Ge ologish		
APPROVED BY	5000000	TITUE	DATE
CONDITIONS OF APPROVAL, IF ANY:			