Submit 3 Copies to Appropriate District Office

APPROVED BY ---

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

-- DATE ---

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.

87504-2088	30-025-30721	
	5. Indicate Type of Lease STATE	FEE (
	6 State Oil & Gas Lease No.	

1.0. DOX 2000	30-025-30721		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 8	5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	STATE X FEE 6. State Oil & Gas Lease No. 857948		
CONTROL MATINES AND DEPORTS OF MATINES			
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF	DO DI LIO DACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PER	MIT. Lease Paints of Only Agreement Paints		
(FORM C-101) FOR SUCH PROPOSALS.)	VACUUM GRAYBURG SAN ANDRES UNIT		
1. Type of Well:			
OSE WELL OTHER			
2. Name of Operator	8. Well No.		
TEXACO PRODUCING INC.	122		
3. Address of Operator	9. Pool name or Wildcat		
P. O. Box 3109 Midland, Texas 79702	VACUUM GRAYBURG SAN ANDRES		
4. Well Location			
Unit Letter H: 1336 Feet From The NORTH	Line and 660 Feet From The EAST Line		
	ige 34-EAST NMPM LEA County		
10. Elevation (Show whether D	VF, RKB, RT, GR, etc.)		
//////////////////////////////////////			
11. Check Appropriate Box to Indicate N	lature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
DUIL OR ALTER CASING			
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB		
OTHER:	OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all partinent details, and work) SEE RULE 1103.	I give pertinent dates, including estimated date of starting any proposed		
1. BASIN #7 SPUD 22 in. HOLE AT 3:30pm 5-22-90. DRILL T 2. RAN 10 JTS OF 18 5/8, 87.5#, K-55, BUTRESS CSG. SET 3. HALLIBURTON CEMENTED w/ 650 SX CLASS H w/ 2% Cacl 5-23-90. DID NOT CIRC. RAN TEMP. SURVEY. TOC AT 25'. R/ Cacl2 @ 15.6ppg. CIRC 25 SX. 4. INSTALL HEAD & test to 350#. TEST CSG. TO 600# FOR 3 5. WOC TIME 35 1/4 HOURS FROM 4:45pm 5-23-90 TO 4:00 6. DRILL TO 1546'. TWIST OFF. REC FISH. RAN 35 JTS OF 1 7. HALLIBURTON CEMENTED w/ 1500 SX CLASS H w/ 2% Cac 100 SX. INSTALL HEAD & TEST TO 350#. 8. NU BOP AND TEST TO 3000#.	TAT 400'. 12 & 1/4# FLOCELE @ 15.6ppg. PLUG DOWN AT 4:45pm AN 1 in. TUBING. CEMENTED w/ 100 SX CLASS H w/ 2% 30 MIN. FROM 5:30-6:00am 5-25-90. 0am 5-25-90. 3 3/8, 48#, H-40, ST&C CSG. SET AT 1546'. cl2 @ 15.6ppg. PLUG DOWN @ 5:00am 5-28-90. CIRC		
9. WOC TIME 52 1/2 HOURS FROM 5:00am 5-28-90 TO 9:30am 5-30-90.			
10. TEST CSG. TO 700# FOR 30 MIN. FROM 11:30am TO 12:00pm 5−30−90. 11. DRILLING 12 1/4 HOLE.			
•			
I hereby certify that the information above is true and complete to the best of my knowledge and b	pelief.		
	R DRILLING SUPERINTENDENT DATE 05-30-90		
TYPE OR PRINT NAME C. P. BASHAM	TRLEPHONE NO. 915-688462		
The Court Time	-		
(This space for State Use) Drig. Signed by	JUN 0 & 199A		
Paul Kautz	A C 16 19 19 19 19 19 19 19 19 19 19 19 19 19		

- TITLE -

Geologii