BLM Roswell District CONTACT RECEIVING OFFICE FOR NUMBER Modified Form No. Form 3160-5 UNITED STATES NM060-3160-4 OF COPIES REQUIRED (July 1989) (Other instructions on reverse LEASE DESIGNATION AND SERIAL NO. DEPARTMENT OF THE INTERIOR side) (Formerly 9-331) BUREAU OF LAND MANAGEMENT NM-93 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT-" for such proposals.) UNIT AGREEMENT NAME WELL X OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR West Corbin Federal Southland Royalty Company 3a AREA CODE & PHONE NO WELL NO. ADDRESS OF OPERATOR 21 21 Desta Dr., Midland, TX 79705 915-686-5600 10. FIELD AND POOL, OR WILDCAT LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* South Corbin (Wolfcamp) See also space 17 below.) 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA At surface 1980'FNL & 510' FWL Sec. 18, T18S, R33E 12. COUNTY OR PARISH 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) NM Lea 3843' GR. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT ABANDONMENT* SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE (Other) Set & Cement Casing CHANGE PLANS REPAIR WELL (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Spudded well @1000 hrs. MST on 12/03/90. Set 13-3/8" 48# H-40 csg @380'. Cmt w/400 sx Class C + 2% calcium chloride + 1/4 pps Celloflake. Circulated 140 sx. excess cmt.

100

 $C_{(1)}$