

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-30802

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
857948

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
VACUUM GRAYBURG SAN ANDRES UNIT

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO PRODUCING INC.

8. Well No.
153

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

9. Pool name or Wildcat
VACUUM GRAYBURG SAN ANDRES

4. Well Location
Unit Letter C : 2630 Feet From The WEST Line and 660 Feet From The NORTH Line

Section 2 Township 18-SOUTH Range 34-EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GR-4016', KB-4029'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. TIH & SET RBP @ 4690'. TEST TO 3000#.
2. COMPUTALOG PERFORATED w/ 2 JSPF 4578-4600, 4616-28, 4658-64. 80 HOLES.
3. DOWELL ACIDIZED w/ 4200 GAL 28% NEFE. 5-7-90. SWAB 3 HOURS REC 95 BLW.
4. TIH & RESET RBP @ 4572'. TEST TO 3000#.
5. PENWOOD PERF w/2 JSPF 4528-40, 4544-62. 60 HOLES. DOWELL ACIDIZED w/ 3200 GAL 28% NEFE. 5-10-90.
6. SWAB 10 HRS. 5-11-90. REC 26 BNO, 78 BLW & 67 BFW. TIH RESET RBP @ 4490' & TEST TO 3000#
7. PENWOOD PERF w/ 2 JSPF 4342-47, 4358-62, 4370-78, 4402-15, 4426-30, 4438-44. 80 HOLES. DOWELL ACIDIZED w/ 4000 GAL 28% NEFE. 5-12-90. SWAB 21 HRS. REC 26 BNO, 185 BLW & 67 BFW.
8. TOH WITH RBP. RAN TUBING, PUMP AND RODS. SN @ 4827'.
9. PUMP TEST. PREP TO POTENTIAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham TITLE DRILLING SUPERINTENDENT DATE 06-01-90

TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use)

ORIGINAL SIGNATURE AND STATION

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 08 1990