		N.M. Oil 🗍 s	. Division
(June 1990) DEPARTMI	NITED STATES ENT OF THE INTERIOR F LAND MANAGEMENT	P.O. Box 1980 Hobbs, NM 882	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.
Do not use this form for proposals to	S AND REPORTS ON WE drill or to deepen or reentry OR PERMIT—" for such pro	to a different reserve	NM-59392 6. If Indian, Allottee or Tribe Name volr.
SUBM	IT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
I. Type of Well			
Oil X Gas Well Other Ame of Operator			8. Well Name and No. Lusk AHB Federal #1
YATES PETROLEUM CORPORATION	u (505)	748–1471)	9. API Well No.
3. Address and Telephone No. 105 South 4th St., Artesia,			30-025-30808 10. Field and Pool, or Exploratory Area EASK LUSE
4. Location of Well (Footage, Sec., T., R., M., or Survey 800' FNL & 1650' FEL of Sec		it B, NWNE)	Undesignated Delaware 11. County or Parish, State Lea Co., NM
12. CHECK APPROPRIATE BO	X(s) TO INDICATE NATU	RE OF NOTICE, R	
TYPE OF SUBMISSION		TYPE OF AC	
Notice of Intent			Change of Plans
Subsequent Report	X Recompletio		New Construction
	Casing Repa		Water Shut-Off
Final Abandonment Notice	Altering Cas	sing	Conversion to Injection Dispose Water
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly sta give subsurface locations and measured and true v			f starting any proposed work. If well is directionally drilled,
8-20-96 - Moved in and rigg TOOH with tubing, tubing ar ulated off RBp at 10568'. on/off tool.	ed up pulling unit. achor and mud anchor. Get on RBP. Could no	TOOH with pump TIH with tubi ot get RBP to u	ng and on/off tool. Circ-
TIH with dump bailer and du TIH with CIBP and set at 10	imped 35' of cement of 260'. Capped CIBP with 200H with logging tool:	n RBP at 10568' ith 35' of ceme s. TIH with 4"	. TOOH with dump bailer. nt. TIH with logging tools casing guns and perforated
8454-8547' (1 SPF - Bone Sp with packer and tubing. Se 8-22-96 - Acidized perforat sealers. Swabbed. Shut we	orings). TOOH with ca et packer at 8368'. tions 8425-8457' with	asing guns and	rigged down wireline. TIH
8-23-96 - Swabbed Release TIH with 4" casing guns and TOOH with casing guns and r RBP at 8071' and tested to 7948-7954' with 1500 gallor	ed packer. TOOH with 1 perforated 7948-795 rigged down wireline. 1000 psi. Set packet	4' w/14 .42" ho TIH with RBP, r at 7973'. Ac	les (2 SPF - Bone Springs). packer and tubing. Set idized perforations
14. I hereby certify that the foregoing is true and correct Signed		ons Technician_	Dute Aug. 29, 1996
(This space for Federal or State office use)			
Approved by Conditions of approval, if any:	Title	АС Г	CEPTED FOR RECORD
Title 18 U.S.C. Section 1001, makes it a crime for any pe	ron knowingly and willfully to make to a	Ny department on accurate	SEP 2 3 1996
or representations as to any matter within its jurisdiction.	term knowingsy and withouty to make to af	by department of agency of the	Difficul States any raise, licitious for fraudulent statements

.

	act a	
*See Instruction on Reverse Side	BLM	
71 1144	MODPONEAST (1)	

=

.



Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals 7. If SUBMIT IN TRIPLICATE 1. Type of Well 0 Gas 0 Well 0 Gas 2. Name of Operator 8. We 2. Name of Operator 1. YATES PETROLEUM CORPORATION (505) 748-1471) 3. Address and Telephone No. 10. Fi 105 South 4th St., Artesia, NM 88210 10. Fi 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Ur 800' FNL & 1650' FEL of Section 35-T19S-R32E (Unit B, NWNE) 11. C CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION 12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION 12 Othec of Intent Recompletion 13 Subsequent Repon Plugging Back D 14 Final Abandonment Notice Altering Casing D	NM-59392 Indian, Allottee or Tribe Name Unit or CA, Agreement Designation II Name and No. Lisk AHB Federal #1 I Well No. <u>30-025-30808</u> eld and Pool, or Exploratory Area adesignated Delaware ounty or Parish, State Lea Co., NM R OTHER DATA Change of Plans New Construction Non-Routine Fracturing
SUBMIT IN TRIPLICATE 1. Type of Well Gas Well Well Well Other 2. Nume of Operator Li YATES PETROLEUM CORPORATION (505) 748-1471) 3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210 4. Location of Well (Footage, Sec., T. R., M., or Survey Description) Ur 800' FNL & 1650' FEL of Section 35-T19S-R32E (Unit B, NWNE) II. C 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION INotice of Intent Abandonment IS Subsequent Report Plugging Back IS Subsequent Report Plugging Back IS Subsequent Report Other IS Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progres subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work J* 8-24-96 - Swabbed. Shut well in. 8-27-96 - Unset packer and RBP. TOOH with packer and RBP. Rigged up w CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" caperforated 7490-7516' w/22 .42" holes as follows: 7490-7496' and 7502-Delaware). TOOH with casing guns and rigged down wireline. TIH with 4" caperforated 7490-7516' w/22 .42" holes as follows: 74	Il Name and No. usk AHB Federal #1 t Well No. <u>30-025-30808</u> eld and Pool, or Exploratory Area <u>adesignated Delaware</u> <u>bunty or Parish, State</u> <u>Lea Co., NM</u> R OTHER DATA Change of Plans New Construction
Out State of Operator 2. Name of Operator Li YATES PETROLEUM CORPORATION (505) 748-1471) 3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210 105 South 4th St., Artesia, NM 88210 10. Fi 4. Location of Well (Focage, Sec., T., R., M., or Survey Description) Ur 800' FNL & 1650' FEL of Section 35-T19S-R32E (Unit B, NWNE) 11. C 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O Image: Casing Repair 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progregore subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 - Swabbed. Shut well in. 8-27-96 - Unset packer and RBP. TOOH with packer and RBP. Rigged up w CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" ccaperforated 7490-7516' w/22. 42" holes as follows: 7490-7496' and 7502-20-206' and 7502-20-206' and 7502-20-206' and 7502-20-206' and 7502-20-206' and 7502-20-206' and 7200'. Capped CIBP with 35' of cement. TIH with 4" ccaperforated 7490-7516' w/22. 42" holes as follows: 7490-7496' and 7502-20-206' and 7502-20-206' and 7502-20-206' and 7502'.	usk AHB Federal #1 Well No. <u>30-025-30808</u> eld and Pool, or Exploratory Area adesignated Delaware Dunty or Parish, State Lea Co., NM ROTHER DATA Change of Plans New Construction
YATES PETROLEUM CORPORATION (505) 748-1471) 3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 10. Fi 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. C 800' FNL & 1650' FEL of Section 35-T19S-R32E (Unit B, NWNE) 11. C 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment X Subsequent Report Plugging Back Final Abandonment Notice Altering Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progive subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)* 8-24-96 - Swabbed. Shut well in. 8-25-26-96 - Swabbed. Shut well in. 8-27-96 - Unset packer and RBP. TOOH with packer and RBP. Rigged up w CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" cca 01BP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" cca perforated 7490-7516' w/22. 42" holes as follows: 7490-7496' and 7502- Delaware). TOOH with casing guns and rigged down wireline. TIH with F Set packer at 7412'. Acidized perforations 7490-7516' w/2000 gallons 7 </td <td>I Well No. <u>30-025-30808</u> eld and Pool, or Exploratory Area <u>adesignated Delaware</u> <u>ounty or Parish, State</u> <u>Lea Co., NM</u> <u>R OTHER DATA</u> Change of Plans New Construction</td>	I Well No. <u>30-025-30808</u> eld and Pool, or Exploratory Area <u>adesignated Delaware</u> <u>ounty or Parish, State</u> <u>Lea Co., NM</u> <u>R OTHER DATA</u> Change of Plans New Construction
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210 10. Fil 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Ur 800' FNL & 1650' FEL of Section 35-T19S-R32E (Unit B, NWNE) 11. C 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Image: Notice of Intent Abandonment Image: Notice of Intent Abandonment Image: Notice of Intent Image: Network State St	30-025-30808 eld and Pool, or Exploratory Area adesignated Delaware ounty or Parish, State Lea Co., NM R OTHER DATA Change of Plans New Construction
4. Location of Well (Footage, Sc., T. R., M., or Survey Description) UT 800' FNL & 1650' FEL of Section 35-T19S-R32E (Unit B, NWNE) 11. C 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment X Subsequent Report Plugging Back Final Abandonment Notice Altering Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progive subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 - Swabbed. Shut well in. 8-27-96 - Unset packer and RBP. TOOH with packer and RBP. Rigged up w CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" caperforated 7490-7516' w/22. 42" holes as follows: 7490-7496' and 7502-Delaware). TOOH with casing guns and rigged down wireline. TIH with packer at 7412'. Acidized perforations 7490-7516' w/2000 gallons 7	eld and Pool, or Exploratory Area idesignated Delaware Dunty or Parish, State Lea Co., NM R OTHER DATA Change of Plans New Construction
800' FNL & 1650' FEL of Section 35-T19S-R32E (Unit B, NWNE) II. C 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O TYPE OF SUBMISSION TYPE OF ACTION In Notice of Intent Abandonment Image: Subsequent Report Plugging Back Image: Subsequent Report Plugging Back Image: Subsequent Report Other Im	Lea Co., NM ROTHER DATA Change of Plans New Construction
TYPE OF SUBMISSION TYPE OF ACTION Image: Notice of Intent Abandonment Image: Abandonment Image: Subsequent Report Image: Abandonment Image: Abandonment Image: Final Abandonment Notice Image: Altering Casing Image: Altering Casing Image: Final Abandonment Notice Image: Altering Casing Image: Altering Casing Image: Final Abandonment Notice Image: Altering Casing Image: Altering Casing Image: Final Abandonment Notice Image: Altering Casing Image: Altering Casing Image: Final Abandonment Notice Image: Altering Casing Image: Altering Casing Image: Final Abandonment Notice Image: Altering Casing Image: Altering Casing Image: Final Abandonment Notice Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing Image: Altering Casing	R OTHER DATA Change of Plans New Construction
TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment X Subsequent Report Abandonment Final Abandonment Notice Plugging Back Image: Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progregive subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 Swabbed. Shut well in. 8-25-26-96 8-27-96 Swabbed. Shut well in. 8-27-96 Unset packer and RBP. TOOH with casing guns and rigged down wireline. TIH with 4" caperforated 7490-7516' w/22.42" holes as follows: 7490-7496' and 7502-Delaware). TOOH with casing guns and rigged down wireline. TIH with packer at 7412'.	Change of Plans New Construction
Notice of Intent Abandonment X Subsequent Report Plugging Back Final Abandonment Notice Altering Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progive subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 Swabbed. Shut well in. 8-25-26-96 Swabbed. Shut well in. 8-27-96 Unset packer and RBP. TOOH with packer and RBP. Rigged up w CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" caperforated 7490-7516' w/22 .42" holes as follows: 7490-7496' and 7502-Delaware). TOOH with casing guns and rigged down wireline. TIH with packer at 7412'. Acidized perforations 7490-7516' w/2000 gallons 7490-7516' w/2000 gallon	New Construction
X Subsequent Report Final Abandonment Notice Plugging Back I Final Abandonment Notice I Altering Casing Other I Other I Other I Subsequent Report I Altering Casing Other I Other I Itering Casing	New Construction
X Subsequent Report Plugging Back Image: Casing Repair Final Abandonment Notice Altering Casing Image: Casing Repair 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progive subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 Swabbed. Shut well in. 8-25-26-96 Swabbed. Shut well in. 8-27-96 Unset packer and RBP. TOOH with packer and RBP. Rigged up we CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" caperforated 7490-7516' w/22 .42" holes as follows: 7490-7496' and 7502-Delaware). TOOH with casing guns and rigged down wireline. TIH with packer at 7412'. Acidized perforations 7490-7516' w/2000 gallons 7	
Final Abandonment Notice Casing Repair Altering Casing Intering Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progres subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 Swabbed. Shut well in. 8-25-26-96 Swabbed. Shut well in. 8-27-96 Unset packer and RBP. TOOH with packer and RBP. Rigged up we CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" cas perforated 7490-7516' w/22 .42" holes as follows: 7490-7496' and 7502-Delaware). TOOH with casing guns and rigged down wireline. TIH with perforations 7490-7516' w/2000 gallons 7490-75	Hou-Routine Practating
Final Abandonment Notice Altering Casing Other Notice Hatering Casing Other Notice Hatering Casing Notice Hatering Casing Other Notice Hatering Casing Other Hatering Casing Oth	Water Shut-Off
 (Not Control of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progres subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 - Swabbed. Shut well in. 8-25-26-96 - Swabbed. Shut well in. 8-27-96 - Unset packer and RBP. TOOH with packer and RBP. Rigged up we CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" caperforated 7490-7516' w/22.42" holes as follows: 7490-7496' and 7502-Delaware). TOOH with casing guns and rigged down wireline. TIH with perforated 7412'. Acidized perforations 7490-7516' w/2000 gallons 7400-7516' w/2000 gallons 7400-7516'	Conversion to Injection
 Con 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any progress subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 - Swabbed. Shut well in. 8-25-26-96 - Swabbed. Shut well in. 8-27-96 - Unset packer and RBP. TOOH with packer and RBP. Rigged up we CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" car perforated 7490-7516' w/22 .42" holes as follows: 7490-7496' and 7502-Delaware). TOOH with casing guns and rigged down wireline. TIH with perforations 7490-7516' w/2000 gallons 7 	Dispose Water e: Report results of multiple completion on Well
give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 8-24-96 - Swabbed. Shut well in. 8-25-26-96 - Swabbed. Shut well in. 8-27-96 - Unset packer and RBP. TOOH with packer and RBP. Rigged up w CIBP and set at 7880'. Capped CIBP with 35' of cement. TIH with 4" ca perforated 7490-7516' w/22 .42" holes as follows: 7490-7496' and 7502- Delaware). TOOH with casing guns and rigged down wireline. TIH with p Set packer at 7412'. Acidized perforations 7490-7516' w/2000 gallons 7	pletion or Recompletion Report and Log form)
8-28-96 - Released packer. TOOH with tubing and packer. Rigged up wir casing guns and perforated 6650-6662' w/13 .42" holes (1 SPF - Delaware casing guns and rigged down wireline. TIH with RBP, packer and tubing. Tested RBP to 1500#. Set packer at 6590'. Acidized perforations 6650- gallons 7-1/2% iron control acid. Swabbing. 8-29-96 - Swabbing. Unset packer. TOOH with RBP, packer and tubing.	vireline. TIH with sing guns and 7516' (1 SPF - oacker and tubing. 2-1/2% iron control celine. TIH with 4" c). TOOH with Set RBP at 6754'. 6662' with 1500
14. I hereby certify that the foregoing is true and correct	<u></u>
signed Kusty The Operations Technician	Date Aug. 29, 1996
(This space for Federal or State office use)	
Approved by Title Title Title	

*See Instruction on Reverse Side

