Submit 3 Copies

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-30851 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATE FEE DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. 857948 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" VACUUM GRAYBURG SAN ANDRES UNIT (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: GAS [WELL X OTHER 2. Name of Operator R. Well No. TEXACO PRODUCING INC. 156 3. Address of Operator 9. Pool name or Wildcat Midland, Texas 79702 P. O. Box 3109 VACUUM GRAYBURG SAN ANDRES 4 Well Location Unit Letter C: 660 Feet From The NORTH 1330 Feet From The WEST _ Line and __ Line **NMPM** 18-SOUTH Range 34-EAST LEA Section Township County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) // GR-3998', KB-4011' Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORARILY ABANDON **PULL OR ALTER CASING CASING TEST AND CEMENT JOB** OTHER: COMPLETION OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. MIRU XPERT, DRILL OUT TO PBTD OF 4815', TESTED CASING TO 3000#. 10-24-90. 2. PENWOOD RAN GR-CCL FROM 4803' TO 4000'. PERF w/ 2 JSPF: 4502-05, 4518-24, 4589-94, 4601-35, 4672-80, 70 HOLES, HALLIBURTON ACIDIZED WITH 4000 GAL 15% NEFE. SWAB 117 BLW IN 3 HOURS 10-26-90. 3. TH WITH RBP. SET @ 4995' & TEST TO 3000#. PERF w/ 2 JSPF: 4302-10, 4316-18, 4325-32, 4338-43, 4360-64, 4388-93, 4424-30, 4448-54, 4463-67, 4478-90. 118 HOLES. HALLIBURTON ACIDIZED WITH 5300 GAL 15% NEFE. SWAB 75 BLW IN 3 HOURS 10-28-90. 4. MOVED RBP TO 4292' & TESTED TO 3000#. PERF w/ 2 JSPF: 4226-34, 4258-62, 4272-81. 42 HOLES. HALLIBURTON ACIDIZED WITH 3300 GAL 15% NEFE. SWAB 33 BLW IN 2 HOURS 10-30-90. 5. RE-ACIDZED PERFS 4226-4281 WITH 3000 GAL 15% NEFE 11-1-90. SWAB 45 BLW IN 7 HOURS 11-2-90. 6. TOH WITH RBP. TIH WITH 2 7/8 TUBING, PUMP & ROD. 7. PUMPED 24 HOURS 11-6-90. RECOVERED 114 BNO & 934 BFW. 8. TESTING, PREP TO POTENTIAL. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 1cw H

____ DRILLING SUPERINTENDENT _ DATE 11-12-90 SIGNATURE C. P. Basham TELEPHONE NO. 915-6884620 TYPE OR PRINT NAME C. P. BASHAM CRICINAL POMED BY JERRY SEXTON (This space for State Use)

DISTRICT LEGITLEVISOR