	UNITED STATES RTMEI OF THE INTER REAU OF LAND MANAGEMEI		0 30 70	Expires A 5, LEASE DESIGN	areau No. 1004-0135 areast 31, 1985 ATION AND BERIAL NO. 16882 068882	
(Do not use this form for p	IOTICES AND REPORTS proposals to drill or to deepen or pluy PLICATION FOR PERMIT—" for such	back to a different reserv			LOTTER OR TEIBE NAME	
WELL X CAS WELL OTHER DEC 13 12 AN '90			NH '90	7. UNIT AGBEEMENT NAME		
2. NAME OF OPERATOR Yates Drilling Company and MYCO Industries, Appo. 4				8. FARM OR LEASE NAME		
3. ADDRESS OF OPERATOR		es, Atteg.		Federal	30	
	eet, Artesia, NM 88210 Hou clearly and in accordance with a			1 10. FIRLD AND P	GOL, OR WILDCAT	
1650' FSL & 660' FWL				LUSK Delaware West 11. SBC., T., B., M., OR BLK. AND BURVEY OR ARMA		
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, BT, GR, etc.)				Sec. 30-195-32E 12. COUNTY OR PARISHI 13. STATE		
	3526'GR			Lea	NM	
	Appropriate Box To Indicate	Nature of Notice, Ke				
				T REPORT OF:	[]	
FRACTURE TREAT	MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREAT SHOOTING OR ACT	MENT	ALTE	RING WELL	
REFAIR WELL	CHANGE PLANS	(Other) Intermediate Casing X (NOTE: Report results of multiple completion on Well				
(Other) 17. DESCRIDE PROPOSED OR COMPLETE proposed work. If well is di nent to this work.) *	DOPERATIONS (Clearly state all pertin irectionally drilled, give subsurface lo	Completion	or Recompleti	on Report and	Log form.)	
at 2418. at 4222. stages. Lite, 5# Calseal "C" + 29 340 bbls Howco L: PD at 10 at 2250 100% exc #1, 200 1528'. Tagged 1 and 2% 0 drill or	<pre>joints new 8 5/8" ST&C, .77' Float collar set .75'. Ran 10 centraliz Stage 1: Cemented wi # Gilsonite, 1/4# Floce + 100 sx. Howco Lite, % CaCl. PD at 2:40 PM, s. off DV too, no retur ite, 12# NaCl + 2% CaCl 0:00 PM, 11-27-90. WOC '. Loaded hole with 100 cess Howco Lite. Tagge sx. Howco Lite with 5# Pumped plug #2, 300 sx plug #2 at 874'. Pumpe CaCl. Circulated 15 sx ut. Notified Vince wit M and #3 11-27-90 @ 4:00</pre>	at 4139.42'. Te ers and 3 cement th 1000 gals. Su le, 2% CaCl + 15 5# gilsonite, 1/ 11-27-90. Test ns. Stage 2: 1 and 100 sx. "C" 6 hrs. Ran temp # brine. Held f d with 1" top of salt and 5% CaC . Howco Lite wit d plug #3, 450 s . to pit. WOc 1 h Hobbs BLM #1 1	exas patt baskets perflush o sx. pr 4# Floce to 900# 500 gals ' + 2% Ca b. survey full, no f cement Cl. WOC ch 5# sal sx. of Ho l6 hrs. P	erned guid . Cemento , 325 sx. emium plus le, 2% Cau , hold OK . Superflo Cl. No re . Top of loss. Pro at 2248'. 3 hrs. To t and 3% of wco Lite rep to tes	de shoe set ed in 2 Howco s, 0.12% Cl and 250 sx. Circulate w/ ush, 1400 sx. eturns. cement found ep to 1" with Pumped plug agged plug at CaCl. WOC 3 hrs with 5# salt st BOP and	
18. I hereby certify that the foregol	φ .	Ducture of the			12 12 00	
SIGNED Jaren J. K		Production Clerk	<u>د</u>	DATE	12-12-90	
(This space for Federal or State	e office use)					
APPROVED BY CONDITIONS OF APPROVAL,				DATE		
	*C !	nt on Roverse Side				

'See Instructions on Keverse Side

.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.