

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31131
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1733-1
7. Lease Name or Unit Agreement Name NEW MEXICO -L- STATE
8. Well No. 11
9. Pool name or Wildcat VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3986, KB-4001'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator TEXACO EXPLORATION AND PRODUCTION INC.
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	4. Well Location Unit Letter A : 604 Feet From The NORTH Line and 856 Feet From The EAST Line Section 1 Township 18-SOUTH Range 34-EAST NMPM LEA County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: COMPLETING <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU XPRT. CLEAN OUT TO PBTD OF 6250'. TESTED CASING TO 3000# FROM 4-4:30pm 4-26-91. (30 MIN)
2. COMPUTALOG RAN GR-CBL-CCL FROM 6250' TO 4500'. PERF w/ 4 JSPF: 6145-50, 6159-63, 6170-73, 6189-92. 60 HOLES. HALLIBURTON ACIDIZED w/ 4200 GAL 15% NEFE. PUMPED 10 BO & 126 BW IN 24 HRS ON 5-22-91.
3. TIH & SET RBP @ 6125'. TEST TO 3000#. PERF w/ 4 JSPF: 5984-86, 5992-94, 5998-6002, 6026-29, 6054-58, 6066-71, 6088-92. 96 HOLES. HALLIBURTON ACIDIZED w/ 4700 GAL 15% NEFE. SWAB 21 BLW IN 5 HRS 5-23-91.
4. TOH WITH RBP. TIH w/ TBG., PUMP & RODS. PUMP 24 HRS. 06-03-91. RECOVERED 17 BO, 157 BW & 18 MCF.
5. TIH & SET RBP @ 5978' & TESTED TO 3000#. PERF w/ 4 JSPF: 5956-70. 56 HOLES. HALLIBURTON ACIDIZED w/ 2200 GAL 15% NEFE. SWAB 12 BO & 12 BLW IN 8 HRS. 06-9-91.
6. TOH WITH RBP. TIH WITH PUMP. PUMP 24 HRS. ON 06-23-91. RECOVERED 51 BO & 217 BW.
7. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C.P. Basham/cwh TITLE DRILLING SUPERINTENDENT DATE 06-24-91

TYPE OR PRINT NAME C. P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY: