

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Encl. Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
30-025-~~91025~~

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
VB-34

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  
Pronto AJF State

1. Type of Well:  
OIL WELL  GAS WELL  OTHER P&A WELL

8. Well No.  
1

2. Name of Operator  
YATES PETROLEUM CORPORATION

9. Pool name or Wildcat  
~~Undec. Strawn~~ *Reever Penn*

3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location  
Unit Letter G : 2310 Feet From The South Line and 2236 Feet From The East Line  
Section 10 Township 18S Range 35E NMPM lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3909' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 11300'. Reached TD 6-21-91. Verbal permission obtained from Jerry Sexton, NMOCD, Hobbs, NM, to P&A well. Well plugged as follows:  
6-29 - 6-30-91. TIH open ended. Circulated 5 hrs. Spot Class "H" cement plugs as follows:  
#1 10905-11005' - Strawn w/40 sacks  
#2 10060-10160' - Wolfcamp w/40 sacks  
#3 6452-6552' - Bone Springs w/40 sacks  
#4 4913-5013' - San Andres w/40 sacks  
#5 3775-3875' - 9-5/8" casing shoe w/40 sacks  
#6 1758-1858' - Rustler w/40 sacks  
#7 Surface - w/10 sacks

Clean pits and weld on dry hole marker. Rig released 1:30 AM 6-30-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: *Juanita Goodlett* TITLE: Production Supervisor DATE: 7-11-91  
TYPE OR PRINT NAME: Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY: *Harry W. Wink* TITLE: OIL & GAS INSPECTOR DATE: OCT 25 1993  
CONDITIONS OF APPROVAL, IF ANY: