

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Meridian Oil Inc.		8. FARM OR LEASE NAME Bondurant Federal	
3. ADDRESS OF OPERATOR P.O. Box 51810, Midland, TX 79710-1810		3a. AREA CODE & PHONE NO. 915-686-5767	9. WELL NO. 6
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface I,2310 FSL & 430' FEL		10. FIELD AND POOL, OR WILDCAT Buffalo (Yates)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.1, T-19-S,R-32-E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3684.7' GR	12. COUNTY OR PARISH Lea	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) PLUGGED AND ABANDONED <input checked="" type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) add "Federal" to	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

API No. 30-025-31331

7-28-91 DRILLED WELL TO 3800'. RIH W/WIRELINE AND LOGGING TOOL, STUCK, WORKED LOGGING TOOL, NO MOVEMENT. COULD NOT WORK OVER BRIDLE W/OS.
7-30-91 FISHING, CUT AND THREAD WL. LINE BALLED UP BELOW TOOL. TRIED TO WORK DOWN.
7-31-91 ATTEMPTED TO PULL WL. WL PARTED. LOGGING TOOL STILL IN HOLE. WORKED SPEAR INTO WL, NO RECOVERY.
8-1-91 CONTINUED FISHING. CIRC'D AND COND. HOLE W/ MUD. WASHED AND REAMED.
8-2-91 REAMED & WORKED FISH. WASHED & REAMED TO BTM. LOGGED WELL.
8-3-91 SPOT 150 SXS C 2% CACL2 AT 3700', WOC, TAGGED AT 3327'. SET CMT PLUG 3000'-2820', SPOT CMT PLUG 1720'-1620', SPOT CMT PLUG 655'-SURFACE. WELL PLUGGED AND ABANDONED.

PLUGGING WITNESSED BY JACK JOHNSON W/BLM

Approved for Release by the Bureau of Land Management
License No. 1000-1000-1000
Bureau of Land Management is completing.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>Maria J. Peco</u>	TITLE <u>Production Asst.</u>	DATE <u>1-6-92</u>
(This space for Federal or State office use)		
APPROVED BY _____	TITLE _____	DATE <u>1-8-92</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side