

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31334
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-1860
7. Lease Name or Unit Agreement Name Atlantic 32 State
8. Well No. #3
9. Pool name or Wildcat Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P&A
2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>800</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>18S</u> Range <u>33E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3746.6 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: TD ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7 7/8" hole @ 5120' @ 9:45 pm 8/8/91

8/8/91 P&A well @ 10:30 pm

Set 100' plug w/35 sks C Neat @ 5120-5020'
Set 100' plug w/35 sks C Neat @ 3050-2950' (top of Yates @ 3000')
Set 100' plug w/50 sks C Neat @ 1410-1310' (top of Rustler @ 1360')
Set 100' plug w/40 sks C Neat @ 475-375' (btm of csg @ 426')
Set surface plug w/10 sks C Neat
Installed dry hole marker
RR @ 2:30 am 8/10/91

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Vickie Teel TITLE Production Analyst DATE 8/13/91

TYPE OR PRINT NAME Vickie Teel

TELEPHONE NO. 623-6601