

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31392
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LH-1840
7. Lease Name or Unit Agreement Name CORBIN STATE
8. Well No. 2
9. Pool name or Wildcat SOUTH CORBIN WOLFCAMP
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3898.3 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator MERIDIAN OIL INC.	3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810	4. Well Location Unit Letter H : 510 Feet From The EAST Line and 1980 Feet From The NORTH Line Section 16 Township 18-S Range 33-E NMPM LEA County
---	--	--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: ADDED PERFS & ACIDIZED <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-18-92 PERFORATE WOLFCAMP 11040-11080' 2SPF (82 HOLES) ACDZ W/110 GALS TRETOLITE P190-34K PARAFFIN INHIBITOR AND FOLLOWED W/4000 GAL 15% PENTAL 100+123 BS.
8-20-92 TO 8-22-92 SWAB TEST, TRACE OF OIL, NON PRODUCTIVE. SET CIPB @ 11150'.
8-23-92 TO 8-26-92 SET CR @ 10950'.SQZ PERFS 11040 TO 11080' W/550 SXS H CEMENT.
8-27-92 TO 8-29-92 DRLG OUT CR, CMT AND CIPB @ 11150'.
8-30-92 PERF 10856-10932'.
9-01-92 ACDZ 10856-10932' W/4400 GALS PENTAL 100. PUT WELL ON PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE PAT HENRY TITLE PRODUCTION ASST. DATE 12-15-92

TYPE OR PRINT NAME PAT HENRY TELEPHONE NO. 915 688-6899

ORIGINAL SIGNED BY JERRY SEXTON
(This space for State Use) DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 18 92