

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-31414

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG - 2945

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Maralo SV 16 State

1. Type of Well:

OIL WELL ☐ GAS WELL ☐ OTHER ☐ Dry

2. Name of Operator

Maralo, Inc.

3. Address of Operator

P. O. Box 832, Midland, Texas 79702 0832

4. Well Location

Unit Letter C : 2310 Feet From The West Line and 530 Feet From The North Line

Section 16 Township 18S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3931 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-23-92 Notified NMOCC of intent to plug and abandon. RIH & set CIBP @ 5710' Capped w/ 35' cement.

3-24-92 Displaced hole w/10# salt gel mud. Cut off csg @ 4870'. POH & LD 121 jts 5 1/2" 17# N-80 csg.. spotted 100' cmt plug from 4820' to 4920' across 5 1/2" csg. stub.

3-25-92 RIH & tagged plug @ 4920'. Pull up to 3862'. Spotted cmt plug from 3762-3862'. Spotted 100' cmt plug from 1750' - 1850'. spotted 100' cmt plug from 350' - 450'. Not required to tag remainder of plugs per Buddy Hill w/NMOCC. Cut off wellhead. Spotted 10 sx surface plug. Installed plate & dry hole marker. Well P & A'd

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Brenda Coffman

TITLE

Agent

DATE

9-1-92

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Kary M. Hill

TITLE

OIL & GAS INSPECTOR

DATE

APR 21 1993

CONDITIONS OF APPROVAL, IF ANY: