

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31494
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-1860
7. Lease Name or Unit Agreement Name Atlantic 32 State
8. Well No. #6Y
9. Pool name or Wildcat Buffalo Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P&A
2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202
4. Well Location Unit Letter <u>B</u> : <u>341</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>32</u> Township <u>18S</u> Range <u>33E</u> NMMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3751.5 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>TD</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7 7/8" hole @ 4560' 5/21/91 @ 5:30 am

12/23/91 P&A well @ 5:00 pm
Set 60 sk plug @ 4560-4360'
Set 50 sk plug @ 2818-2718'
Set 40 sk plug @ 1408-1308'
Set 40 sk plug @ 464-364' (btm of csg @ 414')
Set 10 sk plug @ surface
Install dry hole marker
RR @ 11:00 pm 12/23/91

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Vickie Teel TITLE Drlg/Prod Analyst DATE 12/27/91
TYPE OR PRINT NAME Vickie Teel TELEPHONE NO. 623-6601

(This space for State Use)

APPROVED BY Conrad D. Seil TITLE OIL & GAS INSPECTOR DATE 12/27/91
CONDITIONS OF APPROVAL, IF ANY: