

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002531879
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1306-2
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	124
9. Pool Name or Wildcat	VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>B</u> : <u>1020</u> Feet From The <u>NORTH</u> Line and <u>1519</u> Feet From The <u>EAST</u> Line Section <u>6</u> Township <u>18-SO</u> Range <u>35-EA</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3976', KB-3990'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	CLEAN OUT & ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-28-00: MIRU. TEST CSG & PKR TO 750 PSI FOR 30 MIN-OK. NDWH. NUBOP. REL PKR. TIH W/BIT. PU WS TO 1700'.
 11-29-00: TAG FILL @ 5877'. RU REV UNIT & C/O 443' FILL TO 6320'. (PERFS 5917-6056). CIRC CLN. PULL BIT TO 5860'.
 11-30-00: LOWER BIT. TAG @ 6320'. NO FILL. TIH W/PKR, SN, TBG. ATTEMPT TO SET PKR @ 6008'. PULL PKR TO 5818. SET PKR. LOAD & TEST CSG & PKR TO 600-OK. ACIDIZE GLORIETA PERFS 5917-6056 W/2000 GALS 15% NEFE W/10% XYLENE.
 12-01-00: RU SWAB. FL @ SURF. REL PKR.
 12-04-00: TIH W/TBG.
 12-05-00: TIH W/PUMP OUT PLUG, PKR, ON/OFF TOOL, TBG. SET PKR @ 14' KB @ 5855'. REL ON/OFF TOOL. CIRC W/PKR FLUID. LATCH BACK ONTO ON/OFF TOOL. NDBOP. NUWH. TEST CSG & PKR TO 600 PSI FOR 30 MIN. CHART FOR NMOCD. INSTL INJ LINE. RIG DOWN. RETURN WELL TO WIW.
 12-10-00: ON 24 HR OPT. INJ'G 464 BWPD @ 1849 PSI.
 FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 1/4/01

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY: _____ TITLE _____

DATE _____

Descriptive No. 12-93

JCS