Submit 3 Copies to Appropriate District Office

State of New Mexico Energy,

erals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.

LOG TOPS: Top Salt 1496' Base Salt 2896" Yates 3090' Seven Rivers 3494' 03-17-93 WO completion Thereby certify that the information above is true and signature TYPE OR PRINT NAME DOTOTHEA (This space for State Use)	Oevens	belie. Le Regulatory Ana	alyst DATE March 22, 1993 TELEPHONE NO. (915) 684-744 MAR 2 4 1993
LOG TOPS: Top Salt 1496' Base Salt 2896" Yates 3090' Seven Rivers 3494' 03-17-93 WO completion Thereby certify that the information above is true and signature	Oevens		
IOG TOPS: Top Salt 1496' Base Salt 2896" Yates 3090' Seven Rivers 3494' 03-17-93 WO completion Thereby certify that the information above is true and	^		alyst DATE March 22, 1993
.3% CFR3. Cemt circ'd to LOG TOPS: Top Salt 1496' Base Salt 2896" Yates 3090' Seven Rivers 3494' 03-17-93 WO completion	1 complete to the best of my knowledge and	belief.	
.3% CFR3. Cemt circ'd to LOG TOPS: Top Salt 1496' Base Salt 2896" Yates 3090' Seven Rivers 3494' 03-17-93 WO completion			
LOG TOPS: Top Salt 1496' Base Salt 2896" Yates 3090' Seven Rivers 3494'			
.3% CFR3. Cemt circ'd to LOG TOPS: Top Salt 1496' Base Salt 2896"			
.3% CFR3. Cemt circ'd to LOG TOPS: Top Salt 1496'			
.3% CFR3. Cemt circ'd to			
.3% CFR3. Cemt circ'd to			
.3% CFR3. Cemt circ'd to			
Cemt + Q# esl + 1/4# fl	ocele, tailed in w/200 o surface. Hole size	0 sx 50/50 poz n : 7 7/8". WOC.	nix cemt + .6% Halad 9 +
03-16-93 Ran 89 jts 5 1/	/2" 15.50# csg. Set @	3700'. Cemted	csg w/700 sx Halco Light
size: $12\frac{1}{4}$ ". WOC 12 hrs.	,		The second secon
03-10-93 Spud @ 4:00PM. with 350 sx Cl. "C" cemt	RU & ran 11 jts 8 5 w/2% CaCl2. Plug do	/8" 24# K-55 Csq wn @ 11 PM. Cemt	g. set at 455'. Cemented t circ'd to surface. Hole
Describe Proposed or Completed Operation work) SEE RULE 1103.			
	Clarify Mark 1	OTHER:	
OTHER:			
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB XX
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. 🖾 PLUG AND ABANDONMENT 🗌
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
		SOB	SEQUENT REPORT OF:
11. Check Ap NOTICE OF INTE	opropriate Box to Indicate		
//////////////////////////////////////	3700'	Noting of New P	<u> </u>
	10. Elevation (Show whether		V/////////////////////////////////////
Section 2	Township 19S R	ange 32E	NMPM Lea County
Unit Letter J: 2310	Feet From The South	Line and23:	10 Feet From The East Line
4. Well Location			
P. O. Box 832, Midland	d. TX 79702		9. Pool name or Wildcat Buffalo (Yates)
Maralo, Inc. 3. Address of Operator			2
2. Name of Operator			8. Well No.
1. Type of Well: OIL GAS WELL X WELL	OTHER		Bondurant 2 State
(FORM C-10	01) FOR SUCH PROPOSALS.)		
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERV	POSALS TO DRILL OR TO DEEPEN POIR. USE "APPLICATION FOR PE		7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS			
SUNDRY NOTIC			V-3750
SUNDRY NOTIC			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTIC			S. Indicate Type of Lease STATE X FEE
SUNDRY NOTIC	Santa Fe, New Mexico		S Indigate Tyme of Legge

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 2 3 1993
OCD HOBBS OFFICE