

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002532026
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-1306-1
7. Lease Name or Unit Agreement Name	VACUUM GRAYBURG SAN ANDRES UNIT
8. Well No.	126
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3995', KB-4008'	

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
P.O. BOX 730, HOBBS, NM 88240

4. Well Location
Unit Letter L : 1980 Feet From The SOUTH Line and 1308 Feet From The WEST Line
Section 1 Township 18-S Range 34-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3995', KB-4008'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/1/94 - 6/4/94

- MIRU, TOH W/ RODS, PMP, & TBG. TAGGED @ 4814' (PBDT). SPTD 1000 GALS AMMONIUM BICARBONATE ACROSS PERFS FROM 4257'-4728'. SION.
- TIH W/ PKR. SPTD 1000 GALS 15% NEFE HCL @ 4750'. SI 1 HR, REVERSED OUT SPOT. SET TREATING PKR @ 3470', LOADED AND TSTD BS. ACIDIZED PERFS FROM 4257'-4728' W/ 10,000 GALS 15% NEFE HCL. MAX P = 2050#, AIR = 4 BPM. SI 1 HR & SWABBED BACK.
- SCALE SQZD W/ 4 DRUMS TH-793 IN 48 BFW, OVERFLUSHED W/ 400 BFW. SION.
- TOH W/ PKR. TIH W/ RODS, PMP, & TBG. RETURNED WELL TO PRODUCTION.
OPT 7-1-94 PUMPING BY ROD PUMP: 65 BOPD, 504 BWPD, 35 MCFD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engr Asst DATE 7/15/94

TYPE OR PRINT NAME Monte C. Duncan Telephone No. 397-0418

(This space for State Use)

APPROVED BY _____ TITLE DISTRICT I SUPERVISOR DATE JUL 19 1994

CONDITIONS OF APPROVAL, IF ANY: