

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-32389
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-0321
7. Lease Name or Unit Agreement Name: Buckeye 11 State
8. Well No. #1
9. Pool name or Wildcat Reeves Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Harvey E. Yates Company

3. Address of Operator
P.O. Box 1933, Roswell, New Mexico 88202

4. Well Location
Unit Letter **B** : **990** feet from the **North** line and **2,150** feet from the **East** line
Section **11** Township **18S** Range **35E** NMPM **Lea** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,906' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/21/01 RIH w/tbg to 8,265'. Spot plug w/25 sxs cmt.

5/22/01 Tag plug @ 8,063'. Circ 10# mud. Spot 25 sxs cmt @ 5,215-5,015'. Spot 25 sxs cmt @ 3,509'. Tag @ 3,251'. Spot 25 sxs cmt @ 2,197'.

5/23/01 Cut csg @ 525'. Circulate on annulus between 8 5/8" x 13 3/8" csg. Perforate @ 448'. Circulate backside annulus. No circulation on 5 1/2". Gary Wink, NMOCD gave approval to squeeze 100 sxs cmt, leaving csg full. Install dry hole marker. Level pit & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianna Rodgers TITLE Production Analyst DATE 06/08/2001

Type or print name Dianna Rodgers

Telephone No. 505-623-6601

(This space for State use)

APPROVED BY [Signature] TITLE Field Sup DATE 10-10-01

Conditions of approval, if any: