

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO. 30-025-32538
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-473

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name  La Rica "32" State
2. Name of Operator Mewbourne Oil Company	
3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88241	8. Well No.
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>18S</u> Range <u>34E</u> NMPM Lea County	9. Pool name or Wildcat E-K Bone Spring
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3879' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/14/94 thru 12/19/94

MIRU plugging unit. Set CIBP @ 9000'. Displaced hole w/plug mud. Spotted 25 sx. of cement on top of CIBP. Spotted 25 sx. cement plugs @ 5260' and 3250'. Shot off 5-1/2" casing at 2383'. Set 35 sx. cement plug at 2435'. Tagged top of cement at 2280'. Set 35 sx. cement plug at 457'. Set 10 sx. cement plug at surface. Cut off wellhead and installed P & A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Engineer DATE January 5, 1995  
TYPE OR PRINT NAME \_\_\_\_\_ TELEPHONE NO. \_\_\_\_\_

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE APR 20 1995  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

**RECEIVED**

JAN 06 1995

W. D. HOBBS  
OFFICE