

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32791	
5. Indicate Type of Lease STATE ☒ FEE ☐	
6. State Oil / Gas Lease No. B-1113-1	
7. Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT	
8. Well No. 197	
9. Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	
3. Address of Operator PO BOX 3109, MIDLAND, TX 79702	
4. Well Location Unit Letter <u>D</u> : <u>717</u> Feet From The <u>NORTH</u> Line and <u>1093</u> Feet From The <u>WEST</u> Line Section <u>6</u> Township <u>18-S</u> Range <u>35-E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3982' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	FISH/CO/ADD PERFS/ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-13-01: MIRU. PULL RDS & PMP. WRK STUCK TBG.
8-14-01: RAN FP. STUCK @ 4550. CHEM CUT 2 7/8" TBG @ 4480. TIH W/OS, BS, JAR & DC'S ON WS TO 3973.
8-15-01: JAR STUCK TBG. JAR LOOSE. TIH W/LEAD BLOCK ON TBG. TAG @ 4510.
8-16-01: TIH W/BIT & CSG SCRAPER TO 4500. TIH W/PKR SET @ 4190. TEST CSG FR 4190-SURF TO 800 PSI-OK. REL PKR.
8-17-01: RAN CMT RET & SET @ 4480. TBG PARTED @ 230.
8-20-01: TIH W/OS TO 230. LATCH ONTO PARTED TBG.
8-21-01: RAN BIT & COIL TBG. TAG CMT @ 2130. DRLG CMT TO 2750.
8-22-01: DRILL CMT 2750-4000.
8-23-01: DRILL 4000-4447. RAN FP TOOL. TAG @ 4068. RAN SNKR BAR. TAG @ 2330. SPUD TO 3506. TIH W/RD. TAG @ 2416.
8-24-01: TIH TO 4475. RAN FP & TAG @ 2255.
8-27-01: DRILL 2360-3044.
8-28-01: DRILL 3044-3230. TWISTED OFF 2 1/16" TBG.
8-29-01: TIH W/TAPER TAP & TBG TO 1020.
8-30-01: WRK STUCK TBG.
9-07-01: RAN FP. TAG @ 3842. TIH W/BIT & WS TO 4285.
9-12-01: SET CIBP @ 4273. TIH W/WINDOW MILL, WATERMELON, HYDRILL. TAG CIBP @ 4277. TIH W/WHIPBACK, WHIPSTOCK, MILL. SET WHIPSTOCK @ 4277-4263. MILL WINDOW 4263-4269. 9-14-01: MILL 4269-4272. MILL 4272-4277. 9-17-01: DRILL NEW FORMATION 4277-4351, 4351-4408, 4494, 4568, 4620, 4720. TAG TD 9-25-01. SET PKR @ 4220.
9-26-01: ACIDIZE OPEN HOLE 4261-4720 W/15,000 GALS 15% HCL. RU SWAB. 10-02-01: TIH W/RDS. LD RDS. REL PKR. TIH W/WS.
10-08-01: TIH W/PSI TOOL, MOTOR, SEAL, PUMP, & 2 3/8" TBG. START UP. 10-09-01: RIG DOWN. START WELL UP.
10-11-01: ON 24 HR OPT. PUMPING 43 BO, 717 BW, & 50 MCF. (SUB PUMPED) FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 10/22/01
TYPE OR PRINT NAME J. Denise Leake Telephone No. 915-688-4752

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____ DATE _____