

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-32871
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> Injection		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron Texaco Corporation		6. State Oil & Gas Lease No. B-1722
3. Address of Operator P.O. Box 3109 Midland, Texas 79702		7. Lease Name or Unit Agreement Name: New Mexico "L" State
4. Well Location Unit Letter <u>A</u> : <u>1310</u> feet from the <u>North</u> line and <u>10</u> feet from the <u>East</u> line Section <u>1</u> Township <u>18S</u> Range <u>34E</u> NMPM Lea County		8. Well No. 16
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Vacuum Drinkard

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 5 1/2" CIBP @ 7550 spot 25 sxs. Plug 7550 to 7350 (Drinkard) Tag @ 7281
2. Displace hole w/MLF, 9.5# Brine w/25# P/BBL
3. Spot 25 sxs. Plug 3800 to 3600 (Queen)
4. Spot 25 sxs. Plug 2800 to 2600 (Yates, B-Salt) Tag @ 2527
5. Spot 50 sxs. Plug 1600 to 1200 (8 5/8 shoe, T-Salt) Tag @ 1087
6. CIRC cmt. 30 to surf w/15 sxs.
7. Install dry hole marker (1/16/02)

*Vacuum G-4A PM project
new plug set
Glorieta & Grayburg
AK*

Glorieta 5837-5889
Grayburg 4011-4240

I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 1-16-02

Type or print name Jimmy BAGLEY Telephone No. 915 683-4996
(This space for State use)

APPROVED BY Johnny Robinson TITLE COMPLIANCE OFFICER DATE JUL 15 2002

Conditions of approval, if any: