Office Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103			
District I	Energy, Minerals and Natural Resources			Revised March 25, 1999			
1625 N. French Dr., Hobbs, NM 88240 District II	French Dr., Hobbs, NM 88240				WELL API NO.		
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-32872			
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			5. Indicate Type of Lease			
District IV	Santa Fe, NM 87505			STATE X FEE 6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505		·		O. State On 6	t Gas Least No.		
	CES AND REPORTS	ON WELL	9	7 Long Name	an I Init A	-	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Unit Agreement Name:			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				New Mexico "L" State			
1. Type of Well:							
Oil Well Gas Well	Other X Injection						
2. Name of Operator				8. Well No.			
Chevron Texaco Corporation				17			
3. Address of Operator P.O. Box 3109 Midland Toyon 70702				9. Pool name or Wildcat			
P.O. Box 3109 Midland, Texas 79702 4. Well Location				Vacuum Drinkard			
4. Wen Eccation							
Unit Letter H:	2560 feet from the	Nortl	h line and 10) feet fr	om the East	lina	
				<u></u>	om die <u>Last</u>	line	
Section 1	Township	18S	Range 34E	NMPM	Lea County		
	10. Elevation (Show	whether D	PR, RKB, RT, GR, etc	:.)			
11 Check A	Inpropriate Roy to I	ndicata N	Jatura of Notice	Parant on Oth	Dete		
11. Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: SUBS				SEQUENT R			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					EPURT OF: ALTERING CASIN	IC [
_			TEMEDIAL WOR	`	ALTERING CASIN	В	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIE	LLING OPNS.	PLUG AND	Х	
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN	ID 🗆	ABANDONMENT		
	COMPLETION		CEMENT JOB				
OTHER:			OTHER:			П	
12. Describe proposed or completed	operations. (Clearly st	ate all pert	inent details, and giv	e pertinent dates.	including estimated	date of	
starting any proposed work). SE	E RULE 1103. For Mu	ıltiple Com	inletions: Attach wel	llbore diagram of	faronocad commission		
recompilation.				Nous	um G-GA PA	1 reas	
1. Set 5 1/2" CIBP @ 7500 spot	25 sxs. Plug 7500 to 73	300 (D ri nka	ard) Tag @ 7237	onds!	lans at		
		`	, ,	my	lays at	ayla	
2. Displace hole w/MLF, 9.5#	Brine w/25# P/BBL			gus v			
3. Spot 25 sxs. Plug 3800 to 36	00 (Queen)						
4. Perf 6 hole @ 2600, sqz. w/50 sxs. 2600 to 2400 (Yates, B-Salt) Tag @ 2378							
$C_{i} = C_{i}$							
5. Perf 6 hole @ 1600, sqz. w/125 sxs. 1600 to 1200 (8 5/8 shoe, T-Salt) Tagg @ 1098							
6. Perf 6 hole @ 300, CIRC cm	it. 300 to surf (5 ½ x 8 4	5/8\ w/140	eve		000		
		,, 0, 11, 110	ons.				
7. Install dry hole marker (1/11)	/02)						
hereby certify that the information al	bove is true and comple	te to the be	est of my knowledge	and baliaf			
	/ comple	AC to die o		and belief.			
SIGNATURE /	Ť	TITLE/	MANAGER		DATE_ / 02		
Type or print name Timms	BAGLEY			Teler	phone No. 915 683.	_UQQ/_	
This space for State use)	211-27			1 6161	Maio 140. [13 6653	7170	
A PROPERTY STOP A	2.0 -		IMPLIANCE OFFIC	ER			
APPPROVED BY A Conditions of approval, if any:	Whinson.	TITLE			_DIUTE 1 5 2002	<u>!</u>	
on sitions of approval, it any:	W				-		
NI IM	N .						

<u>ح</u> ک