

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32964
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-201-2
7. Lease Name or Unit Agreement Name Buckeye 2 State
8. Well No. #1
9. Pool name or Wildcat Reeves, Bone Spring
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3896'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P&A
2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202 505/623-6601
4. Well Location Unit Letter 0 : 660 Feet From The South Line and 1650 Feet From The East Line Section 2 Township 18S Range 35E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3896'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/21/95 TD 7 7/8" hole @ 9282'

6/23/95 P&A well as follows:

Set 40 sk plug @ 8450-8550'  
Set 40 sk plug @ 6120-6220'  
Set 40 sk plug @ 5030-5130'  
Set 60 sk plug @ 3450-3550'  
Set 40 sk plug @ 1750-1850'  
Set 10 sk plug @ surface

Cut off well head & Install dry hole marker  
RR @ 11:30 pm 6/23/95

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bob Williams TITLE Drlg Superintendent DATE 7/3/95  
TYPE OR PRINT NAME Bob Williams TELEPHONE NO. 505/623-6601

(This space for State Use)

APPROVED BY Larry W. Hill TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: