

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

| FORMATION | TOP | BOTTOM | DESCRIPTION, CONTENTS, ETC. |
|-----------|------|--------|-----------------------------------|
| DELAWARE | 5883 | 7526 | SANDS CONTAINING OIL, GAS & WATER |

38. GEOLOGIC MARKERS

| NAME | TOP | |
|-------------|-------------|------------------|
| | MEAS. DEPTH | TRUE VERT. DEPTH |
| TOP SALT | 1690 | |
| BASE SALT | 2820 | |
| YATES | 3476 | |
| QUEEN | 4135 | |
| SAN ANDRES | 4946 | |
| DELAWARE SD | 5883 | |
| BONESPRINGS | 7526 | |