Form 3160-5 (August 1999)

UNITED STATES DEPARTMF OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oll Cons. Division FORM APPROVED

1625 N. Fre. ... Dr. OMB NO. 1004-0135
Expires: November 30, 2000

Hobbs. NM 88240. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			NM 010388 6. If Indian, A	NM 010388 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or C	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well X Oil Well Gas Well Other 2. Name of Operator				8. Well Name and No. SEMSSAU #3	
3a. Address 3000 N. Garfield, Suite 175 Midland, Texas 79705 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 380' FNL & 350' FWL, Sec. 33, T175, R33E, Unit Ltr D			10. Field and Maljamar G	30-025-33220 10. Field and Pool, or Exploratory Area Maljamar Grayburg San Andres 11. County or Parish, State	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REI			REPORT, OR OTI	PORT, OR OTHER DATA	
TYPE OF SUBMISSION	i i	TYPE OF ACTION			
Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. I testing has been completed. Final Abandonment I determined that the final site is ready for final inspersent perfs: 4300-4399' (Grayl: Plans are to MIRU PU. POH w/rods gun and perf Grayburg Sand @ 4258 4276' and 4277' (total 13 holes). w/2% KCl to btm perf. Swab back Work is planned to start immediate.	plete horizontally, give subsurformed or provide the Bond of fifthe operation results in a monotices shall be filed only aftection.) Surg) S. & pump. ND WH & N. 3, 4259', 4260	Fracture Treat Rect New Construction Recc Plug and Abandon Tem Plug Back Wate Cluding estimated starting date of a face locations and measured and trace locations and measured and trace locations are measured and trace locations and measured and trace locations are all requirements, including rect RU BOP. TIH & tag PBIT 11', 4265', 4266', 4267', 4265', 4266', 4267', 4269',	ue vertical depths of a irred subsequent report in a new interval, a Fammation, have been contained and TOH w/tub.	Il pertinent markers and zones. It is shall be filed within 30 days orm 3160-4 shall be filed once ompleted, and the operator has being. TIH w/csg., 4274', 4275', antol acid. Flush PU.	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		Title Regulatory Tech			
Janice Courtney Jani	ce Courtney	Date 6/26/2002			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by		Title	I	Date	
Conditions of approval, if any, are attached. Approval certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations	o those rights in the subject l	or Office			
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section States any false, fictitious or fraudulent statements or re	on 1212, makes it a crime for	any person knowingly and willfull within its jurisdiction.	y to make to any depa	rtment or agency of the United	