Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103	
District I	Energy, Minerals and Natural Resources			Revised March 25, 1999 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION DIVISION			30-025-34051	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			STATE FEE 6. State Oil & Gas Lease No.	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505				E-1582	as Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or	Unit Agreement Name:
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other				"SV" HONEY BEE STATE	
2. Name of Operator				8. Well No.	
MANZANO OIL CORPORATION					
 Address of Operator P.O. BOX 2107 - ROSWELL, NM 88202-2107 				9. Pool name or Wildcat	
4. Well Location					
Unit LetterE:2372feet from theNORTH line and994feet from theWESTline					
Section 22	Township	18S R	ange 35	NMPM LE	A County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3923' KB 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
		dicate N	ature of Notice,	Report or Other	Data
	PLUG AND ABANDON	\boxtimes	REMEDIAL WOR		
	CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A	ND 🗆	
OTHER:			OTHER:		
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 					
1. MIRU Triple N Services, Dig & li		ad hole w	//mud		
2. Pump cement plugs as follows: 30sk plug @ 12,000' 30sk plug @ 10,000'					Sam HIS
30sk plug @ 8,000'					A 18
30sk plug @ 6,000'					
50sk plug @ 3,900' – Shoe Plug – Tag 35sk plug @ 1,400' (t/salt)					
3. Perforate 8 5/8" casing @ 450' & squeeze 100sx from 450'-350' - Tag					
4. Pump 15sk surface plug (60'-surfa		79 5 6	0		()CD
5. Install dry hole marker & clean u	ip location	i i tu Hatak	S FRICE TO TH	ST BE NOTIFIÈ DE 24 E BEGINNING É CE	а., "
Triple N is scheduled to move in ASAP which will be in June PLUGGING OPERATIONS FOR THE C-103					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE	Eng	TITLE	Apart		_DATE5/8/02
Type or print name Mike Hanag	jan		Telepho	ne No.	505-623-1996
(This space for State use),			- <u>-</u>		MAY 1 5 2002
APPPROVED BY	1	TITLE		· · · · · · · · · · · · · · · · · · ·	DATE
Conditions of approval, if any:					^

JC

Cto