

DISTRICT I
1625 French Drive Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, NM 7504-2088

WELL API NO.
30-025-34193

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2148

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Caprock Maljamar Unit

1 Type of Well:
OIL ☐ GAS ☐
WELL ☐ WELL ☐ OTHER ☐ Injection

2. Name of Operator
The Wiser Oil Company

8. Well No.
283

3. Address of Operator
P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

9. Pool name or Wildcat
Maljamar Grayburg San Andres

4. Well Location
Unit Letter O : 1033 Feet From The South Line and 1975 Feet From The East Line
Section 28 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4170'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforate & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/28/99 MIRU Pool Well Service. ND WH. RU BOP. POH w/tbg. LD pkr. RU Computalog WL & perforate San Andres Jackson 4656'-80' w/2 SPF (50 holes). RD WL.

4/29/99 RIH w/5-1/2" x 2-3/8" Baker J-Lok pkr. & 2-3/8" W-7 tbg. Set pkr. @ 4525'. Acidize San Andres Jackson f/4525'-4680' (60 holes) w/4500 gals. 15% HCL NE-FE acid w/120 7/8" ball sealers. ATP 4000# @ 3.6 bpm. MTP 4200# @ 4.5 bpm. ISIP 2880#. 5 min. 2270#. 10 min. 2190#. 15 min. 1810#. 1 hr. SI 1780#. RIH w/2-3/8" tbg. to 4700'. POH w/tbg. & circulate pkr. fluid. Set pkr. Pressure test csg. to 300# for 15 min. Chart ran by Nick Jimenez w/Gandy Corporation.

4/30/99 Place well back on injection - 250 BWPD @ 1000#. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE May 30, 2002
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY GARY W. WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE JUL 2 2002

