State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-8

FILE IN TRIPLICATE	OIL CONCEDIATION DIVISION			Revised 1-1-89
DISTRICT I	OIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505			
P.O. Box 1980, Hobbs, NM 88240			WELL API NO.	
DISTRICT []				025-34374
811 S. 1st Street, Artesia, NM 88210			5. Indicate Type of Lease	
DISTRICT III			FED STAT	
1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.	· · · · · · · · · · · · · · · · · · ·
	TIGES AND DEPONDED			
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agree	ment Name
(FORM	(FORM C-101 FOR SUCH PROPOSALS.)		NODTH HODDS (CISA) INTE	
1. Type of Well:		NORTH HOBBS (G/SA) UNIT		
Oil Well X	Gas Well Other			
2. Name of Operator			8. Well No. 531	
ALTURA ENERGY LTD. 3. Address of Operator				
1017 W. Stanolind Rd., HOBBS,	NIM 00040		9. Pool name or Wildcat	HOBBS (G/SA)
4. Well Location	NM 88240 505/3	97-8200		
L'air Larra				
Unit Letter J : 2120	Feet From The SOUTH	Line and 1500 Feet	From The EAST	Line
Section 32	Township 18S	Pares 2017)	_
32	10. Elevation (Show whether DF, R	Range 38E	NMPM Viiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	LEA County
	3635 GL	RD, RI OR, ER.)		
11. Check	k Appropriate Box to Indicate N	ature of Notice Report or O	ther Data	
NOTICE OF INT	ENTION TO:		EQUENT REPORT C	Λ C .
PERFORM REMEDIAL WORK	PLUG AND ABANDON			
TEMPORARILY ABANDON		RÉMEDIAL WORK	ALTERIN	G CASING
	CHANGE PLANS	COMMENCE DRILLING OPN	S. PLUG & /	ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT	JOB O	
OTHER: WATER SHUTOFF	X	OTHER:		
12. Describe Proposed or Completed Operation	s (Clearly state all pertinent details an	duive pertinent dates in studios		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
1 DIST DDADIGERAL HOUSE				
 PULL PRODUCTION EQUIP. SOUEEZE PERFS AT 4052-751 				
 SQUEEZE PERFS AT 4052-75'. STIMUALATE OPEN PERFS. 				
4. RETURN TO PRODUCTION.				
is known to thoughton.				
\wedge \wedge .	,			
Thereby certify that the information above is tru	e and complete to the best of my knowled	lge and belief.		
SIGNATURE A	1()/ K			0/1
		TITLE PROD ENGR	DATE	7/21/98
TYPE OR PRINT NAME D. NELSON			TELEPHONE NO.	505/397-8200
(This space for State Use)				
APPROVED BY		Tree f		•
CONDITIONS OF ADDROVAL IF ANY	The war is the	_ TITLE	DATE	