

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34644
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTH HOBBS G/SA UNIT
8. Well No. 544
9. Pool name or Wildcat HOBBS; GRAYBURG - SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Altura Energy LTD
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294
4. Well Location Unit Letter P : 925 Feet From The SOUTH Line and 1050 Feet From The EAST Line Section 29 Township 18-S Range 38-E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3646' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Run 5-1/2" Casing** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/24/99: Run 103 jts. of 5-1/2", 15.5#, J-55, I/T&C casing with 11 centralizers and set at 4400'. Pump first stage cement, 225 ~~ss~~ Premium Plus. Circulate 89 sx. cement off top of DV tool (G3477'). Circulate between cement stages. Pump second stage cement, 500 sx. Interfill Cl. C and 50 sx. Cl. C Neat. Circulate 120 sx. cement to surface. Set slips, nipple down, and cut off casing.

Release drilling rig at 9:45 p.m., 7/24/99.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE **BUSINESS ANALYST (SG)** DATE **7/28/99**

TYPE OR PRINT NAME **MARK STEPHENS** TELEPHONE NO. **281-552-1158**

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

TITLE _____ DATE **8/6/99**

CONDITIONS OF APPROVAL, IF ANY: