

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-34869</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name <b>North Hobbs G/SA Unit</b>
2. Name of Operator <b>Altura Energy LTD</b>	8. Well No. <b>623</b>
3. Address of Operator <b>P.O. Box 4294, Houston, TX 77210-4294</b>	9. Pool name or Wildcat <b>Hobbs; Grayburg - San Andres</b>
4. Well Location Unit Letter <b>K</b> : <b>1837</b> Feet From The <b>South</b> Line and <b>2462</b> Feet From The <b>West</b> Line Section <b>29</b> Township <b>18-S</b> Range <b>38-E</b> NMMPM <b>Lea</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3645' GL</b>	

11.

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**  
**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **Spud & Run Surface Casing** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/4/00: MI x RU. Spud 12-1/4" hole @ 10:30 a.m. (NMOC notified).

3/6/00 -

3/7/00: Run 38 jts. 8-5/8", 24#, J-55, ST&C casing with 11 centralizers and set @ 1560'. Cement with 525 sx. PBCZ Cl. C (lead) and 225 sx. PBCZ Cl. C tail. Plug down and circulate 260 sx. to surface. WOC. Cut off casing. Dig 21' of cement (from conductor pipe) out of cellar. Weld on head and nipple up BOP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Business Analyst (SG) DATE 03/08/2000  
TYPE OR PRINT NAME Mark Stephens TELEPHONE NO. 281/552-1158

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: