

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
811 S. 1st Street, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.	30-025- 34906
5. Indicate Type of Lease	FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH HOBBS (G/SA) UNIT
8. Well No.	511
9. Pool name or Wildcat	HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT GR, etc.)	3631 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well Gas Well Other

2. Name of Operator
ALTURA ENERGY LTD.

3. Address of Operator
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200

4. Well Location
Unit Letter D : 1310 Feet From The NORTH Line and 598 Feet From The WEST Line
Section 33 Township 18S Range 38E NMPM LEA County


11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>New Well Completion</u> <input checked="" type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Tag PBTD.
2. Perforate 4102-4294.
3. Acid Stimulate.
4. Run production equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE PROD ENGR DATE 5/2/00

TYPE OR PRINT NAME D. NELSON TELEPHONE NO. 505/397-8200

(This space for State Use)

APPROVED BY _____ TITLE ORIGINAL SIGNED BY CHRIS WILLIAMS DATE 5/2/00

CONDITIONS OF APPROVAL IF ANY: DISTRICT I SUPERVISOR

5