

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

1625 N. French Drive, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-34907
5. Indicate Type of Lease FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT
SECTION 32
8. Well No. 512
9. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator OCCIDENTAL PERMIAN LIMITED PARTNERSHIP	
3. Address of Operator 1017 W STANOLIND RD.	
4. Well Location Unit Letter <u>F</u> : <u>2164</u> Feet From The <u>NORTH</u> Line and <u>2054</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>18-S</u> Range <u>38-E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3631' GL.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work) SEE RULE 1103.

Rig up Pulling Unit 04/25/00
Sqz perforations from 4070' - 4196'.
Reperforate San Andres Zone from 4120' - 4196'. (4 JSPF, 90 degree phasing, 464 holes)
Acidize perms w/6000 gal 15% HCL acid.
RIH w/production equipment. REDA ESP.
Rig Down and Clean Location.

Rig Up Date: 04/25/00
Rig Down Date: 05/03/00

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert N. Gilbert TITLE LIFT SPECIALIST DATE 05/30/00
TYPE OR PRINT NAME R.N. GILBERT TELEPHONE NO. 505/397-8206

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____