

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
-----------	-----	--------	-----------------------------

38.

GEOLOGICAL MARKERS

38.

GEOLOGICAL MARKERS

TOP

TOP

NAME	MEAS. DEPTH	TRUE VERT. DEPTH	NAME	MEAS. DEPTH	TRUE VERT. DEPTH
RUSTLER	820'				
YATES	2552'				
SEVEN RIVERS	2946'				
DELAWARE	4564'				
BONE SPRINGS LIME	7130'				
WOLFCAMP LIME	10360'				
STRAWN	11032'				
ATOKA SHALE	11442'				
MORROW	11950'				

BUREAU OF LABOR STATISTICS
ROSSMITH, GENE

2001 JUL - 3 AM 9:19

RECEIVED