37. SUMMARY OF POROUS ZONE Show all important zones of porosity and contact thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

**FORMATION** 

TOP

воттом

DESCRIPTION, CONTENTS, ETC.

38. G	SEOLOGICAL MARKERS		38. GE		
NAME	TOP			TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH	NAME	MEAS. DEPTH	TRUE VERT. DEPTH
RUSTLER	751'		ATOKA	11,656'	VEICH: DEI TI
YATES	2533'		MORROW	12,243'	
SEVEN RIVERS	2824'		LOWER MORROW	12,516'	
DELAWARE	4530'				
BONE SPRINGS	7167'				
IST SAND	8423'		i		
ND SAND	9117'				
BRD SAND	9901'				
VOLFCAMP	10,521'				
STRAWN	11,211'				