

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
**30-025-35332**

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  
**North Hobbs G/SA Unit**

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

8. Well No.  
**621**

2. Name of Operator  
**Occidental Permian Limited Partnership**

3. Address of Operator  
**P.O. Box 4294, Houston, TX 77210-4294**

9. Pool name or Wildcat  
**Hobbs: Grubb - San Andres**

4. Well Location  
Unit Letter **C** **927** Feet From The **North** Line and **2158** Feet From The **West** Line  
Section **30** Township **18-S** Range **38-E** NMPM **Lea** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
**3655' GL**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **Rm 5-1/2" Casing** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/24/01 -

2/25/01: Rm 109 jts. 5-1/2", 15.5#, J-55, LT&C casing with 12 centralizers and set at 4380'.  
Pump 300 sx. Premium Plus cement (first stage). Bump plug, drop bomb, and open DV tool  
(circulate 84 sx.). Pump second stage cement, 700 sx. Interfill 'C' (lead) and 100 sx.  
Premium Plus (tail). Circulate 289 sx. to surface. Bump plug x nipple down. Set slips  
and rig down.

Release drilling rig at 11:00 a.m., 2/25/01.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Business Analyst (SG) DATE 02/26/01

TYPE OR PRINT NAME Mark Stephens TELEPHONE NO. 281/552-1158

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

5  
C