

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

1625 N. French Drive, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO.	30-025-35342
5. Indicate Type of Lease	FED <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	SOUTH HOBBS (G/SA) UNIT
8. Well No.	240
9. Pool name or Wildcat	HOBBS (G/SA)

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator OCCIDENTAL PERMIAN LTD.	
3. Address of Operator 1017 W STANOLIND RD.	
4. Well Location Unit Letter <u>N</u> : <u>837</u> Feet From The <u>SOUTH</u> Line and <u>1611</u> Feet From The <u>WEST</u> Line Section <u>34</u> Township <u>18-S</u> Range <u>38-E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3613' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RUPU. 10/02/2002  
Stimulate existing perms w/4000 g 15% NEFE HCL acid.  
Perforate San Andres Zone at the following intervals; 4082-88, 4096-98, 4102-05, and 4110-28. 2 JSPF and 120 degree phasing.  
Stimulate new perms w/900 g 15% NEFE HCL acid.  
RIH w/REDA ESP equipment on 132 jts 2-7/8" tbg.  
RDPU and Clean Location.

Rig Up Date: 10/02/2002  
Rig Down Date: 10/13/2002

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert Gilbert TITLE LIFT SPECIALIST DATE 06/01/00  
TYPE OR PRINT NAME R.N. GILBERT TELEPHONE 505/397-8206  
NO.

(This space for State Use)

APPROVED BY GARY TYLBWINK DATE DEC 09 2002  
CONDITIONS OF APPROVAL IF ANY: ORIGINAL SIGNED BY GARY TYLBWINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER